Note: Radiator Parts Not issue at DMS. PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3370 E **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 01.09.21 Date: 84 F.R SI NO# Ref.No: Tan-1 Mchanic Name:Md Rafiqul Islam Engineer Name:Md Jahid Hasan Zone Name: Tangail Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1735251411 Mobile No: **Customer Name:** Ali Akbar Mama vagina engineering Dealer Name: Vadra, Nagoorpur, Tangail Address: 8001 Present Km MD6M14CL5K4P00158 CH NO Full # Customer Complain:-**TVS King Duramax** OL4PK4700455 Model# Raiator Fracture with start problem EN NO Full # 11.10.2020 Sale Date # 1st PS Kms 1St PS Date 28.08.2021 Date of Comp# N/A 01.09.21 Date of Repair# Free service information **3rd Free Service** 2nd Free Service **1St Free Service KMs** Date **KMs** Date **KMs** Date 6203 24.06.21 3,872 02.05.21 1013 23.03.2021 Observation:- we find and checked that the Fan Assy radiator was Fracture and TCI weak. Action Taken:- Please to be replace the radiator & TCI by new one under warranty. Failure Particular Approved Rejected Vendor code Qty Part Name Part NO. SL TCI unit G4060400 1 Radiator G4181080 2 3 4 For Head Office Use Failure Parts Photo **DMS Engineer Head of Service**