

PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD

DMS NO:

Head Office

2972

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No:	Sylhet/Jan/06/296	F.R SI NO	296	Date:	06.01.2021	
Zone Name: Sylhet Sadar		Engineer Name: Tisu Barua		Mchanic Name: Moin Uddin		

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name:	Md.Motiur Rahman			Mobile No:	01742794582		
Address:	Chatok, Sunamganj.				Dealer Name:	Tawsif motors	
Customer Complain:-		CH NO Full #	MD6M14CA8K4K00462		Present Km	12,710	
Oil leakege from front shock absorber		EN NO Full #	AK4KK4809877 31.05.2020		Model #	TVS King Deluxe	
		> Sale Date #					
		Date of Comp#	04.01.2021		1St PS Date	1st PS Kms	
		Date of Repair#	of Repair#				
	Free service information						
4 f		1St Free Service 2nd		2nd F	ee Service 3rd Free Servi		Free Service
		Date	KMs	Date	KMs	Date	KMs
		27.06.2020	945	30.07.20	3,986	29.08.2020	4986

Obserbation:- We checked & found that oil leakege front shock absorber.

Action Taken:- Require to replace this parts under warranty for your approval.


Failure Particular

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	124
1	G4100180	Front shock absorber	(1/	Gabrial			
2	G12180010	XI			The second		E.
3		/\		The state of the s	************		
4			W.A.L		Late 1		3

Failure Parts Photo

For Head Office Use

Engineer



Head of Service

The state of the s

sead Office Use

De Short of the State of the St

DMS