PRODUCT PERFORMANCE FEEDBACK REPORT DMS NO: IFAD MOTORS LTD **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 28.03.2021 Date: Mchanic Name: Md. Shipon Alom Engineer Name: Md. Abdullah Al Ref.No: Habiganj/Mar/352 Zabed Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01913735056, 01902530980 Mobile No: Shahjalal Automobile Md. Asik Ullah Mir Dealer Name: Customer Name: Present Kms # Tvs King Deluxe MD6M14CA814A07911 Lakhai , Habiganj CH NO Full # Address: Model # CNG AK4AJ4022288 Customer Complain:-EN NO Full # Front Shock absorber has been 1st PS Kms 18.10.2020 1St PS Date Sale Date # 28.03.2021 Date of Comp# Date of Repair# 28.03.2021 Free service information 3rd Free Service 2nd Free Service 1St Free Service Date KMs 7950 Date 28.03.2021 KMs Date 3,220 06.01.2021 980 Observation:- We checked & found that front Shock absorber has been broken... 26.11.2020 Action Taken: New one front shock absorber replaced. Approved Rejected Failure Particular Vendor code Qty Part Name 60000297 Part NO. G2100010 SL 01 Front shock absorber 26 12 17 H G4100180 1 3 4 For Head Office Use Man olson by the way Failure Parts Photo Head of Service Kn1812 (2021