	rus	PRODUCT	PERFORMAN	NCE	FEEDE	BACK REPO	ORT	- <u> </u>	
//EAD		IFAD MOTORS LTD						DMS NO:	
	MOTORIUM SPOTOM	Head Office					3079		
		IFAD Tower, Plo				l Area Dhak	a-1208		
	D (A)	II AD TOWEI, THE	t /(IVCVV), ICJSC	<u> </u>		O#- 317	Date:	1/30/2021	
-	Ref.No:	£							
Zone Name: Chittagong					Engineer	Name: Md Farha	Mchanic Name: Faruk		
	Approved by:	Prabir Biswas (Head	of Service,Spare Par	ts & Pr	roduction))			
		r		5		I	(A)		
Customer Name: Selim Mia				Mobile No		Mobile No:	01885336776		
Address: Kagracori,Chittagong				Dea		Dealer Name:	M/S Shatata Enterprise		
Customer Complain:-			CH NO Full #	MD6M14CL9K4P00244			Present Kms # 205 256		
Oil Leakage from rear and front			EN NO Full #	OLADKAA00426			Model #	TVSKING	
shockabsorber			Sale Date #		And the second	11/30/2020	DURAMAX		
			Date of Comp#	No. of the second	AL ALBERTA	1/29/2021	1St PS Date	1st PS Kms	
			Date of Repair#	1.1.2.) (.11/	1/29/2021			
			Free service information						
			1St Free Serv	vice 2nd Free Service		3rd F	ree Service		
			Date	KMs	Date	KMs	Date	KMs	
			12/27/2020	954	26.12	2565			
		w one Front and Rear	Failure F	era Laureana	lar		A CONTRACTOR OF THE CONTRACTOR		
SL		Part NO.	Part Name	e	Qty	Vendor code	Approved	Rejected	
1	SHOCK ABSO	RBER ASSY REAR	G2090100	A THE STATE	(1)	Salar 18			
2	SHOCK ABSO	RBER ASSY FR	G2100010		1	a faighteach ann ann an a			
3			×	44.7	and the second				
4					in the same			T. A.	
			1	harananan k Kajaran	eriografia de la como		kalis produces Vivas	The state of the s	
	Failure	Parts Photo		ace of early sparked?	224	THE WHEN THE STATE OF THE STATE	AND AND SOURCE SERVICE SERVICES		
- Charlet and Thota					2 For I	Head Office Use	•		
			Uood of	Sorvice	Company of the second second	Head Office Use	Spect part de .	DMS	
			Head of	Service	Company of the second second	Head Office Use	Spect part de .	DMS	
			Head of	Art Art	e Francis Singlesor	the breat of the comment	eer.	DMS Charles Charles	