TVS

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD DHAKA METRO

DMS NO: 3412

Head Office

IFA	D Tower	<u>, Plot-7</u>	(New),	Tejgoan	Industrial	Area,	Dhaka-1208	

 Ref.No:
 Dhaka Metro/Jan/12/03
 F.R SI No
 03
 Date:
 12.01.2022

Zone Name: Dhaka Metro Engineer Name: MD. Usuf

Approved by: Kaushik Sarkar (COO IFAD GROUP)

			Mil	nonha	1		
Customer Name:	Sayud Ahmed Rasel	aisal Amed			Mobile No:	016104987	98
Address:	Mirpur, Dhaka				Dealer Name:	Satata as I	nterprise
Customer Complain:-		CH NO Full #	MD6N	MD6M14CA1J4L09506		Present Kms # 13623/	
Oil leakage from rear shock absorber		EN NO Full #	AK4LJ	4694132		NA 1 - 1 - 4	T. (C. (') D.
		Sale Date # 05.01.2021		1	Model #	TVS King Deluxe	
		Date of Comp#	01.05.	2021	2	1St PS Date	
		Date of Repair#					
	9			Free	service informa	ition	
*		1St Free Serv	ice	2nd F	ree Service	/3rd	Free Service
		Date	KMs	Date	KMs	Date	KMs
		28.01.2021	1203	25.02.21	3,212	20.03.2021	4985

Obserbation:- We checked & found that oil leakege Rear shock absorber.

Action Taken:- Require to replace this parts under warranty for your approval.

-			_		
- 2	111	Ira	Dar	ticu	12r

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	SHOCK ABSORBER ASSY	1	Gabrial		
2						
3	-		***************************************			
4						

Fail	lure	Dar	tc D	h	0	+0
ı an	ule	rai	LOF	11	U	w

For Head Office Use

Head of Service Engineer

Approved by Mail.

MithSaha 46/01/2022

DMS

Dris Complete