IFAD MOTORS LTD

Head Office

IFAD TOWER ,07 Tejgaon I/A, Dhako-1208.

DMS JOB NO

F.R SI NO# Ref.No: Habiganj/Oct/324 324 Date: 19.10.2020 Zone Name: Habiganj Zone Md. Abdullah Al Zabed **Engineer Name:**

Approved by: Prabir Biswas (Head of Service & Spare Parts)

Customar Name: Md. Angur Miah Mobile No: 01746607425 Chunagat, Habiganj Address:

Shahjalal Automobile Dealer Name: Customar Complain:-CH NO Full # MD6M14CA8J4A06810 Present Kms # Front Shock absorber has EN NO Full# AK4AJ4213518 Tvs King Deluxe Model # broken. Sale Date # CNG/LPG 26.08.2020 Date of Comp# 16.10.2020 1St PS Date 1st PS Kms Date of Repair # 17.10.2020

Free service information 1St Free Service 2nd Free Service 3rd Free Service Date KMs Date KMs **KMs** Date 24.09.2020 820 17.10.2026 1940

Obserbation:- we checked & found that front Shock absorber has broken.

Action Taken:- New one front shock absorber replaced.

					Northwest Salar and Control	
		Failure Pa	articular			
SL	Part NO	Part Name	/ Qty	Vendor code	Approved	Rejected
	G4100180	Front shock absorber		Gabrial (60000297;	,	
1				G2100010, 04.01.18 H)		
2		7				a
3						
4				7 17.75		
5				- 55		
c .			1		yes as a	1

Failure Parts Photo

For Head Office Use

Johammad Abdullah Al Zahed Senior Service Engineer IFAD MOTORS LTD. Cell: 61701-227974

20/10/2020

Oris Complete Nitu Sahar. 20.10.2020