PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

DMS NO:

Head Office

3348

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

18.08.2021 Date: 309 F.R SI NO Ref.No: Sylhet/Aug/18/309

Mchanic Name: Moin Uddin Engineer Name: Tisu Barua Zone Name: Sylhet Sadar

Approved by: Md. Milon Hossain (Assistant Manager)

e: Soroth Miah				Mobile No:	01749745590			
				Dealer Name:	Tawsif motors			
		MD6M	14CL8K4	P00449	Present Km	12,566		
Customer Complain:- Oil consupmtion high.		OL4PK4600513			Model#	TVS King Duramax		
		31.05.2020						
		17.08.2021			1St PS Date	1st PS Kms		
y								
		1St Free Service 2nd		Free Service	3rd Free Service			
			Date	KMs	Date	KMs		
	29.06.2020	1203	12.08.20	. 4,865	09.10.2020	7986		
i	n:-	Jogonathpur, Sunamgonj. n:- igh. EN NO Full # Sale Date # Date of Comp# Date of Repair# 1St Free Serv	Jogonathpur, Sunamgonj. n:- igh. EN NO Full # MD6M Sale Date # 31.05.2 Date of Comp# 17.08.2 Date of Repair# 1St Free Service Date KMs	Soroth Mian Jogonathpur, Sunamgonj. CH NO Full # MD6M14CL8K4 igh.	Soroth Miah	Soroth Miah Dealer Name: Tawsif mode T		

Obserbation:- We checked & found that the Cyl.Block inner wall scratch.

Action Taken:- Require to replace this parts under warranty for your approval.

		Failure Partic	<u>ular</u>			
CL	Part NO.	Part Name	Qty	Control of the contro	Approved	11 11 11
SL 1	G4011470	CYLINDER	1	Not issue	at Dys	5. 1209
2	G4010070	GASKET CYLINDER	1	DM3 Dens	* V	13/00/
2	G4011350	GASKET CYL HEAD	1	11		
4	G4020130	Piston Kit STD LC	1	11 -	<u> </u>	

For Head Office Use Failure Parts Photo Engineer **Head of Service**

DMS