

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD **Head Office**

DMS JOB NO 2308.

IFAD TOWER .07 Telagon I/A. Dhaka-1208.

IFAD TOWER, 65 Tejguen 1, 19 2 tem											
Ref No:	ctg-Aug-20			F.R SI NO#	201-2020	Date:17-08-2	2020				
	Zone Name: Chittagong			Engineer Name: SUMON DAS							
Zone wame:	Chittagong		· · · · · · · · · · · · · · · ·								
Approved by: Prabir Biswas, GM (Head of Service ,S/Parts)											
						04.074200002					
Customar Name: Hamid Hosan			Mobile No		Mobile No:	01874200992					
Address:	Ali Kadam, Bandarban				Dealer Name:	Abu Sama Motors					
Remarks	CH NO Full #	MD6M14CA0J4L09593									
		EN NO Full #	AK4LJ4095128								
Rear shock Absorber oil leakage RH & LH		Sale Date #	17/11/2019			Present Kms #	17987				
			17.08.2020			Model #	TVS KING				
		Date of Comp#	·				DELUXE CNG				
		Date of Repair #	17.08.2020								
_		Free Cupon service information									
			1St Free Service		2nd Free Service		3rd Free Service				
		Date	KMs	Date	KMs	Date	KMs				
		17.10.2019	1590	13,12.19	2689	23.01.2020	5467				
					cage RH & 1	A)					
Obserbation:-We checked & found that, This rear Shock Absorberoil leakage.											
						20					
a g a			2	AT IS		"	nuit.				
Action Taken:- Those spare parts will have be replaced by warranty purposs.											
Action Taken:- Those spare parts will have be Topiassa at Takens											

Failure Particular									
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected			
1	G2090100	REAR shock absorber	200 H	2020		· ·			
2		×	03	01	1				
3						,			
4				4					
5				4 %	-				
6					1				

For Head Office Use **Failure Parts Photo**

Note: As a special case, Due to lockdown ill.