


IFAD

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD TOWER Of Telagon I/A, Dhako-1208.

Ref.No:	Habiganj/N	ov/328		F.R SI NO#	328	Date:	05.11.2020	
Zone Name:			Engineer Name:		Md. Abdullah Al Zabed			
	y: Prabir Biswas (Head of Service & Sp			Parts)	rts)			
2								
Customar Name:	Md. Mohadis Miah				Mobile No:	01781140088		
Address:	Daragaw , F	, Roshidpur, Habiganj			Dealer Name:	Shahjalal Automobile		
Customar Complain:- CH NO Full #			MD6M14CA5J4A07901		Present Kms #	920		
Front Shock absorber has broken.			Ak4AJ4322712			Model#	Tvs King Deluxe	
		Sale Date #	10.10.2020			Y 72777	CNG/LPG	
		Date of Comp#	05.11.2020			1St PS Date	1st PS Kms	
		Date of Repair #	05.11.2020			345.33.42		
		Free service information						
		1St Free Service 2nd Fr		ee Service	3rd Free Service			
		Date	KMs	Date	KMs	Date	KMs	
		05.11.2020	920			die Greek		
Obserbation:- we ch	ecked & fou			has broken.		Accessor		

Action Taken:- New one front shock absorber replaced

		Failure	Particular	4 4 2	vid. Al	
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G4100180	Front shock absorber	01	Gabrial (60000297)- 030118H	hyaldi-Ari	•
2		→ X	7		wanted (#145)	
3					- Value la	
4					and the second second	
5					Tak	
6					4.15.7	

	Failure Parts Photo						
	\mathbf{G}						
	C= 0 10						
1.1							
(-)A /							
							
7							
and the second							
	33 N.						

For Head Office Use

gall.

Mohammad Abdullah Al Zahed Senior Service Control of Service Control o

Cell: 01701-227974

Tilleano

Nitu Sahee.

Many the