

## PRODUCT PERFORMANCE FEEDBACK REPORT





## **IFAD MOTORS LTD Head Office**

DMS JC No. 2851


IFAD TOWER .07 Tejagon I/A. Dhaka-1208.

		II AD TOVI	-11,07 10	Jguon I/A,	DIIUKU-1200					
Ref.No:	Dhaka 1/N	ov'20/018		F.R SI NO#	18	Date:	22.11.2020			
Zone Name:	Dhaka			Engineer/Sr.Mechanic Name: Yousuf Ali						
Approved by:	Prabir Bisv	vas-GM,Head of Se	ervice & Sp	are Parts-IM		-8 **				
	0				i w					
Customar Name:	SADDAM H	HOSSAIN.			Mobile No:	01912166355				
Address:	SIRAJDIKH.	HAN, Munshiganj			Dealer Name:	Mayer Dowa				
Customar Complain:-		CH NO Full #	MD6M14CA9J4L09382							
Front Shock absorber		EN NO Full #	AK4LJ4893523							
problem.		Sale Date #	18.09.2020 Present Kms #				3099			
		Date of Comp#	22.1	1.2020-	State Constitution of the	Model#	TVS KING Deluxe			
		Date of Repair #				IVIOUEI #				
		Free Cupon service information								
*		1St Free Service 2nd Fr		ee Service	3rd Free Service					
		Date	KMs	Date	KMs	Date	KMs			
		12.10.2020	967	22.11.2020	3099	ne .				
Obserbation:- We	checked &	found that front s	hock abso	rber oil leak	nge/					

Action Taken:- New one Front shockabsorber under warranty replacemant

Failure Particular									
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected			
1	G4100180	Front Shockabsorber	(1 )	paralami in a					
2	Principal	X		and the second s					
3	DANT-AMB	ette	0 19		e V	**			
4				Military and the second second					
5				\$2.					
6	,								

**For Head Office Use Failure Parts Photo** 



charact

lawe