PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 2415 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO 01 Date: 12.01.2022 Ref.No: Dhaka Metro/Jan/12/01 Engineer Name: MD. Usuf Mchanic Name: MD. Usuf **Dhaka Metro** Zone Name: MILON HOSSAIN Approved by: Kaushik Sarkar (COO IFAD GROUP) 01715565321 Customer Name: Ripon Miah Mobile No: Satata as Enterprise Mirpur 10, Dhaka. **Dealer Name:** Address: MD6M14CA0J4L09531 / Present Kms # 12365 **Customer Complain:-**CH NO Full # Oil leakage from front shock absorber EN NO Full # AK4LJ4794115 Model# **TVS King Deluxe** Sale Date # 29.04.2021 Date of Comp# 05.07.2021 1St PS Date Date of Repair# Free service information 1St Free Service 2nd Free Service **3rd Free Service** Date **KMs** Date **KMs** Date **KMs** 24.07.2021 4965 21.05.2021 1230 26.06.21 3,261 Obserbation:- We checked & found that oil leakege front shock absorber. Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular SL Part NO. Part Name Qty Vendor code Approved Rejected G4100180 1 Front shock absorber Gabrial 2 3 4 For Head Office Use Failure Parts Photo **Head of Service** Engineer DMS Approved by