and tomer, cole: 16841231 PRODUCT PERFORMANCE FEEDBACK REPORT **IFAD MOTORS LTD** DMS NO: 3105 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 11.02.2021 F.R SI N 005 Date: Ref.No: Barishal/2021/005 Engineer/Mechanic Name: Polash Chandra Dhaka - Barisal Zone Name: Approved by: Prabir Biswas-GM, Head of Service & Spare Parts-IML. Ø1754521044 Mobile No: SAHERA BEGUM **Customer Name: M R Motors** Dealer Name: Address: Sadar, Barisal Present Km 1407 MD6M14LA9K4A20040 **Customer Complain:-**CH NO Full # Tvs king duramax EN NO Full# AK4AK4236855 Wheel Rim Broken (LH) Model# 25.12.2020 Sale Date # Date of Comp# 27.01.2021 1St PS Date 1st PS Kms Date of Repair# 17.01.21 Free service information **3rd Free Service** 2nd Free Service **1St Free Service** Date KMs KMs Date **KMs** Date 22.01.2021 1254 D

Observation:- We checked & found that Wheel Rim Broken

Action Taken:- Please Replaced the following parts under warranty

Failure Particular						
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G2111090	RIM ASSY	101494	1.0040	HYESCH!	
2		X	523085.	and the state of t	a Brande!	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3	*	/ 1000		Application of the control of the co		
4			2021		ISLPSORT	

Engineer

chanic Name: Poleon Circle

and Office Use

Failure Parts Photo

Head of Service

He

of Sarvice Than