


PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD TOWER ,07 Tejgaon I/A, Dhako-1208.


Rof No:	Habiganj/sap/319		F.R SI NO#	319	Date:	15.09.2020	
	Habiganj Zone		Engineer Name:		 		
	Prabir Biswas (Head of Se	ervice & Spa					
Customar Name:	ABUL KALAM AJAD		alar	Mobile No:	01714536488	3	
Address:	Chunagat, Habiganj	2	Dealer Name:			Shahjalal Automobile	
Customar Complain:- CH NO Full # MD6N		MD6M14	ČA9J4A06895		Present Kms #	(2640)	
Front Shock absorber	has EN NO Full #	AK4AJ481	AK4AJ4813595			Tvs King Deluxe	
broken.	Sale Date #	08.06.2020 12.09.2020			Model #	CNG/LPG	
	Date of Comp#				1St PS Date	1st PS Kms	
8	Date of Repair #	12.09.202	20		un, 1 An entre est est		
	Free service information						
,	1St Free Service		2nd Fr	ee Service	3rd Free Service		
	Date	KMs	Date	KMs	Date	KMs	
μ 6.	02.07.2020	895	12.09.2020	2640			

Obserbation:- we checked & found that front Shock absorber has broken.

Action Taken:- New one front shock absorber replaced.

Failure Particular								
SL	Pàrt NO	Part Name	Qty	Vendor code	Approved	Rejected		
1	°G2100010	Front shock absorbe	91 pc	Gabrial (60000297) 05.02.17 H				
2	OT, G4100180	X	01Pc	Amy On	21011			
3					08/11/2020	2)		
4			9	as as fat as we	001142			

Failure Parts Photo



51, No 2 approved

mi 82020

6/10/2020