
PRODUCT PERFORMANCE FEEDBACK REPORT





DMS JOB NO 3366



Head Office 77 Teiaaon I/A, Dhaka-1208.

INVIV:	ON THAIR I TIN		IFAD TOV	VER,UT I	ejgaon i/A, i	Diluku-1200.			
Ref.No: Chol		Chokoria/august/03			F.R SI NO#	03	Date:	08/28/21	
Zone Name: Chokoriy						Engineer Name:	Md.Ruhul Aı	min Suman	
Approved by: S M Robbani, DGM -Head of Service & Spare					e Parts.	1	lechanoct	Marin)	
1									
Customar Name: Imran						Mobile No:	01885763562	(10 F)	
Address: Jidda bazar			, Oschazare			Dealer Name:	Abu Sama Mot	ors V	
Customar Complain:-			CH NO Full #				Present Kms #	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Shockabsorber oil leakage.			EN NO Full #	AK4KK4303288			Model #	Tvs King DURAMAX	
			Sale Date #	11/04/2023			454 DC Date	1st PS Kms	
			Date of Comp#	22/08/2023	1		1St PS Date	No No	
			Date of Repair #		.	t Information	No	INO	
			Free service information 1St Free Service 2nd Free Service			3rd Free Service			
			1St Free Se			KMs	Date	KMs	
			Date	KMs	Date	5209	04/08/2021	9589	
Obserbation:- We checked & fo			09/05/2021	1107	27/06/2021		04/08/2021	3303	
2			9						
Action Take	en:- Req	uire to repla	ace this parts under	warranty fo	r your approva	l. _			
						\ /			
-				Fail	ure Particular				
SL	Part	: NO	Part Na		Qty	Vendor code	Approved .	Rejected	
1	G209		Rear Shockabso	orber Assy	2	N a	**	A . 40.	
2		II.		to		<i>Y</i>			
3									
4									
5								G	
6				/					
<u> </u>					F 11 1065 - 11-2				
Failure Parts Photo					For Head Office Use				
						21/2/2021			
					Bilen Stihnsahar				