PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: Head Office IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 14.12.2020 F.R SI NO 295 Date: Ref.No: Sylhet/Dec/14/295 Mchanic Name: Moin Uddin Engineer Name: Tisu Barua Zone Name: Sylhet Sadar Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01747467813 Mobile No: Md.Firoj Ali Customer Name: Tawsif motors Dealer Name: Dhopagul, Sylhet. Address: 14,196 MD6M14CA5K4L00244 Present Km CH NO Full # Customer Complain:-EN NO Full # AK4LK4208179 Oil leakege from front shock absorber TVS King Deluxe Model# Sale Date # 28.06.2020 1St PS Date 1st PS Kms 13.12.2020 Date of Comp# Date of Repair# Free service information 3rd Free Service 2nd Free Service 1St Free Service KMs Date Date **KMs** Date 27.09.20 3,865 25.07.2020 22.08.20 Obserbation:- We checked & found that oil leakege front shock absorbey.

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular						
Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	
G4100180	Front shock absorber	(1)	Gabrial			
612100010	\bar{\bar{\bar{\bar{\bar{\bar{\bar{					
		8	100 , 100 (100 (100 (100 (100 (100 (100			
-		4				
		Part NO. Part Name G4100180 Front shock absorber	Part NO. Part Name G4100180 Front shock absorber 1	Part NO. Part Name G4100180 Front shock absorber G210000 Gabrial	Part NO. Part Name Qty Vendor code Approved G4100180 Front shock absorber 1 Gabrial	

KMs

4968

Failure Parts Photo	For Head Office Use			
	Head of Service	Engineer	DMS	
	May 2020	2000	996, 81, 18, 28, 28, 28, 28, 28, 28, 28, 28, 28, 2	