


## PRODUCT PERFORMANCE FEEDBACK REPORT



## IFAD MOTORS LTD Head Office



89,Bir Uttam C.R Datta road,Nasir Trade center Level-12,Banglamotor,Dhaka. F.R SI NO# Date: 23/07/2020 Ref.No: IML/lal/June /2020/07/23 Engineer Name: Md.Kayem Uddin Zone Name: Nilphamari. Approved by: Probir Biswas (Head of Service ,S/Parts& Production) Customar Name: Md.Ainul Haque Mobile No: 01723271663 Nilphamari **Dealer Name:** Habib Enterprise. Address: MD6M14LA5K4P00126 Customar Complain:-CH NO Full # Speedometer Assy doesn't **EN NO Full #** AK4PK4X00150 11 Sale Date # 21/07/2020 Present Kms # work. Date of Comp# 21/07/2020 TVS KING Model# Date of Repair # 21/07/2020 Deluxe Free Cupon service information 3rd Free Service 1St Free Service 2nd Free Service **KMs KMs KMs** Date Date Date

Obserbation:- We checked the vehicles and found that Speedometer doesn't work. Its part is defective.

What is defective. Odometer or speedo needle flanctuation

11

already repair it. So It patrs is change under warranty.

21/07/2020

Failure Particular						
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G5160150	Speedometer Assy	1	TVS		
2			-			
3					# "	
4					:	at a
5						
6				100		

Failure Parts Photo

For Head Office Use

Ortitubalier 25.07,2020 Drys complete