

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD

DMS NO:

Head Office

3407

IFAD Tower, Plo	t-7(New).	Teigoan	Industrial	Area.	Dhaka-1208
-----------------	-----------	---------	------------	-------	------------

Ref.No	: Sylhet/Dec/27/313	F.R SI No	313	Date:	27.12.2021	
						_

Zone Name: Sylhet Sadar	Engineer Name: Tisu Barua	Mchanic Name: Moin Uddin
-------------------------	---------------------------	--------------------------

Approved by: Kaushik Sarkar-COO(IFAD GROUP)

Customer Name:	Sayed Miah				Mobile No:	Nobile No: 01738536222		
Address:	Dirai, Sunamgonj.				M/S Shahporan Motors			
Customer Compla	in:-	CH NO Full #	MD6N	/114CL6K4		Present Km 19,865		
Oil consupmtion high.		EN NO Full #	0L4PK4300307		Model #	TVS King Duramax		
		Sale Date #	05.10.2020					
		Date of Comp#	02.12.2021		1St PS Date	Date 1st PS Kms		
		Date of Repair#					_	
*		Free service information						
		1St Free Service 2nd F		ree Service	3rd Free Service			
		Date	KMs	Date	KMs	Date	KMs	
		15.11.2020	3659	29.12.20	6,985	06.02.2021	10785	

Obserbation:- We checked & found that the engine oil consumption high.

Action Taken:- Require to replace this parts under warranty for your approval.

<u>Failure Particular</u>						
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G4010140	CAM CHAIN	1			
2	G4010070	GASKET CYLINDER	_ 1			
3	G4011350	GASKET CYL HEAD /	1		DMS	
4	G4322970	Piston Kit 1st O/S LC (Ni)	(1	NO ENTRY	54Stem	Boolem

Failure Parts Photo	For Head Office Use					
	Head of Service	Engineer	DMS			
	29/12/21.	Meuil Appron	MihrSahar 28/12/2021 DMS Complete			