PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3205 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 04.03.2021 F.R SI NO# 22 Date: Ref.No: Dhaka/March/22 Engineer Name: Milon Hossain Mchanic Name: Md.Yousuf Zone Name: Dhaka 1 Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Mobile No: 01921-268793 Customer Name: | Jibon Nesa Mayer Dowa W/S Dealer Name: Sirajdikhan, Munshiganj Address: 16904 **Present Kms** CH NO Full # MD6M14CAXK4K00415 **Customer Complain:-**EN NO Full # AK4KK4908799 Oil Consumption High Model# TVS King Deluxe 28.03.2020 € Sale Date # 1St PS Date 1st PS Kms 01.03.2021 Date of Comp# Date of Repair# Free service information **3rd Free Service** 2nd Free Service **1St Free Service KMs KMs Date KMs Date Date** 1406 04.06.2020 2,890 06.07.2020 4687 02.05.2020 Observation:-What Cansur we checked &found that Piston wall scratch. Action Taken:- Require to replace this parts under warranty for approval. **Failure Particular** Approved Rejected Vendor code Qty **Part Name** Part NO. SL Piston Kit 2nd O/S 4S 1 G4320680 1 1 M7010270 **VALVE INTAKE** 2 1 **VALVE EXHAUST** 3 M7010280 1 VALVE STEM OIL SEAL N4011100 4 5 For Head Office Use **Failure Parts Photo Head of Service Engineer DMS** Con so so 12/2021