| | CVS | PRODUCT | Γ PERFORM | ANCI | E FEE | DBACK RE | PORT | 74 |
|--|---------------|-----------------|----------------------------|--------------------------|---------------------------|----------------------|---|-------------------------------------|
| IFAD | | IFAD MOTORS LTD | | | | | | DMS NO: |
| 220 227 | MOTORSLIMITED | Head Office | | | | | | |
| | | IFAD Tower, F | Plot-7(New), T | ejgoa | n Indus | trial Area, | Dhaka-12 | .08 |
| Ref.No: | | | | | F.R SI NO# 06 | | Date: | 10/28/2021 |
| | Zana Namai | B | | Engineer :Hosan Ali | | Mechanic Name: Bipul | | |
| Zone Name: Rangpur Approved by: Md:Billal H | | | n (Denutyman) | rice) Kaushik 5 | | Danken. | | |
| | Approved by. | | at (Depart) manag | 01 0014 | rect you | MONIA C | menere | |
| Customer Name: Habibur rahman/ | | | /Mainul islam Mobile No: | | 01761-869425/01819-957132 | | | |
| | | | · | | | : Habib Enterprise | | |
| Address: Jadur Hat nilphm Customer Complain:- | | | CH NO Full # MD6M14LL5M4D0 | | | | Present Kms # 7522 | |
| Engine OIL consumption high | | | EN NO Full # OL4DM4600146 | | | | - Model # | TVS KING |
| | | | Sale Date # | 8/16/2021 | | | | DRUAMAX plus \ |
| | | | Date of Comp# | 10/15/2021 | | | 1St PS Date | 1st PS Kms |
| | | | Date of Repair# | | | | | |
| | | | Free service information | | | | | |
| | | | 1St Free Serv | Service 2nd Free Service | | ree Service | 3rd Free Service | |
| | | | Date | KMs | Date | KMs | Date | KMs |
| | | | 25.09.21 | 980 | 28.10.21 | 7,522 | | |
| | | . 1026 | SMA Fai | | rticular | | | |
| SL | Р | art NO. | Part Name | <u></u> | Qty | Vendor code | Approved | Rejected |
| 1 | G4320810 (| 514320780 | KIT ENGINE VALVE | | 01 ~ | A. | | -1 |
| 2 | G4322970 | - 10000 | KIT PISTON 6625 | | 01 \ | 1 | | |
| 3 | | | | | | | | d de discription (see Section 1988) |
| 4 | | | | 9 | | | | <u> </u> |
| (1.17 | Failure Pa | rts Photo | T | | Fo | or Head Office | Use | |
| | | | Head of Service | | | Engineer | | DMS |
| | | | 2000 | | | | 1200 | |
| | | | | | | | MchiSnhar 0/12/2021 oms system problem | |
| | | | | | | * | | problem |

Billal Hossain
Dy. Manager (Service)
IFAD MOTORS LTD
Head Office, Dhaka.