## PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Date: 13.12.2020 293 F.R SI NO Ref.No: Sylhet/Dec/13/292 Mchanic Name: Delower Hosain Engineer Name: Tisu Barua Zone Name: Sylhet Sadar Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01781993119 Mobile No: Moin Uddin Customer Name: Tawsif motors Dealer Name: Salotikor, Sylhet. Address: MD6M14CA9K4K00468/ Present Km 14,863 CH NO Full # Customer Complain:-AK4KK4909879 EN NO Full # Oil leakege from front shock absorber TVS King Deluxe Model# 22.06.2020 Sale Date # 1st PS Kms 07.12.2020 1St PS Date Date of Comp# Date of Repair# Free service information 3rd Free Service 2nd Free Service 1St Free Service **KMs** KMs Date **KMs** Date Date 4968 19.09.20 3,659 22.08.20 20.07.2020 Obserbation:- We checked & found that oil leakege front shock absorber. Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular Approved Rejected Vendor code Part Name Qty Part NO. SL Gabrial Front shock absorber G41001807 1 42100010 2 3 For Head Office Use Failure Parts Photo Engineer DMS Head of Service

Failure Parts Photo

Head of Service

Engineer

DMS

White Parts Photo

OMS

Complete

66,000 orde to proceso