## PRODUCT PERFORMANCE FEEDBACK REPORT

## IFAD MOTORS LTD **Head Office**

DMS JOB NO

2496

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

Ref.No:	ef.No: Sunamgonj/Oct/27/26			F.R SI NO#	28	Date:	27.10.2020			
Zone Name:	Sunamgo	onj datol	•	Er	ngineer Name:	Tisu Barua				
Approved by:	Prabir Bis	was, GM -Head of S	M -Head of Service & Spare Parts.							
*			N							
ustomar Name:	Abdullah Al Mamun				Mobile No:	01745456510				
ddress:	Uttar Molli	kpur, Sunamgonj.	Dealer Name:			Sohel Enterprise				
Customar Complain:-		CH NO Full#	MD6M14CA4K4L00302			Present Kms #	4,986			
il leakage from front shock		EN NO Full #	AK4LK4608530 27.07.2020			Model #	Tvs King Delux			
bsorber		Sale Date #					lpg			
		Date of Comp#	20.10.2020			1St PS Date	1st PS Kms			
		Date of Repair #	Pending		no					
		Free service information								
		1St Free Service		2nd Free Service		3rd Free Service				
		Date	KMs	Date	/KMs	Date	KMs			
		20.08.2020	760	18.09.2020	3210	19.10.2020	4362			
hearhation: We	checked & f	ound that oil leaka	ge from fro	ont shock abe	orber .					

ofRep

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular										
SL	Part NO	Part Name	(Qty)	Vendor code	Approved	Rejected				
1	G4100180	Front shock absorber	1	Gabrial						
2		Ø				· ·				
3		N. 194 (94)								
4						*				
5			-							
6	^ &									

For Head Office Use Failure Parts Photo Mis Completi

27.10.2020 TISU BARUA

Service Engineer FAD MOTORS LTD 810/11/2020