	N	ofe: 5 pgs	2 porris 140	155	our at L	MS.	EX: 2	4225588
7	rus	PRODL	Oroblim Slove ICT PERFORMANCE FEEDBACK REPORT					
MOTOPISLIMITED		IFAD MOTORS LTD						DMS NO:
		Head Office						2222
IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208								
Ref.No: Mym-70			-		F.R SI NO#	70	Date:	12.06.21
					::Md Jahid Hasan Mchanic Name		e:Md Rafiqul Islam	
Zone Name: Tangail			(Head of Service,Spare Parts & Produc			·		
	approved by:	Prabir biswas (	lead of Service, Spare Parts & Froduction,					
Customer Name: Babul Sarkar						Mobile No:	1732048389	
			rai			Dealer Name:	Mama vaigna Engineering	
Address: Tangail Customer Complain:-			CH NO Full # MD6M14CLX				Present Km	
	Rear axle broken		EN NO Full # OL4NL4400210				5.511.44	TVS King Deluxe
near unic scotteri			Sale Date #				Model#	· ·
			Date of Comp#	10.06.			1St PS Date	1st PS Kms
			Date of Repair# Pending				N/A	N/A
			Free service informa			ion	,	
			1St Free Service 2nd F			ee Service	3rd Free Service	
			Date	KMs	Date	KMs	Date	KMs
	4		10.06.21 hat the rear axle v	897				
Action Taken:- Please to be replace the rear axle by new one under warranty.  Failure Particular								
CI	Part NO. Part Name					Approved	Rejected	
SL 1	G2110530		Rear axle		€ 1	Vendor code	Approved	Rejected
	02110330	`	incur uxic		<del>10</del>			
2		* * *				×		
	· · · · · · · · · · · · · · · · · · ·							
3	3						2	
4								<u> </u>
	Failure Par	ts Photo	For Head Office Use					
			Head of Service Eng			Engin	eer	DMS
			To so	10	5/2021	100 2021 Jac		Josephalora.
			1 5		1.	( , 0 -	al 1	JWS.
					ts To	sue Joo	0	

spore ports Jose Jone.