

## PRODUCT PERFORMANCE FEEDBACK REPORT





## **IFAD MOTORS LTD Head Office**

DMS JOB NO

2107,

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

Ref.No:	Habiganj/July/311	F.R SI NO#	311	Date:	29.07.2020
Zone Name:	Habiganj Zone	Engineer Name:		Md. Abdullah Al Zabed	
Approved by:	Prabir Biswas (Head of Service & Sp	are Parts)			

Customar Name:	Md. Jo	Md. Josim Miah			Mobile No:	01748173144	
Address:	Cunar	ugat, Habiganj			Dealer Name:	Shahjalal Aotumobile	
Customar Complain:- CH NO Full #		MD6M14CA0J4A07823		Present Kms #	(1120)		
Front Shock absorber has		EN NO Full #	Ak4AJ4320296		Model #	TVS KING DELUXE	
broken.		Sale Date #	08.07.202	0		IVIOGEI #	CNG
		Date of Comp#	29.07.202	0		1St PS Date	1st PS Kms
		Date of Repair #	29.07.202	0			
*		Free service information					
	1St Free Ser		vice 2nd Free Service		3rd Free Service		
×		Date	KMs	Date	KMs	Date	KMs
		29.07.2020	1120				s: °

Obserbation:- we checked & found that Front Shock absorber has broken.

Action Taken:- New one Front Shock absorber replaced.

Failure Particular							
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected	
1	G2100010	Front shock absorbe	1	Gabrial (600002			
2	y	XI	9	. 7	."		
3		/ *		1 9 9		L.	
4					t e		
5				2.5			
6			10				

**Failure Parts Photo** 

For Head Office Use

