

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS: 2131 DMS Complete

	Ref.No:	IML/lal/Ju	ne /2020/08/06		F.R SI NO#	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date:	6/8/2020	
Zone Name: N				Engineer Name		: Md.Kayem Udd			
		,	was (Head of Servi	ce ,S/Parts					
Custo	mar Name:	Md.Mohir	Uddin	5		Mobile No:	01752313722		
Address: Nilpham		Nilphamar	ri 7		¥	Dealer Name: Habil		abib Enterprise.	
Cı	ustomar Com	nplain:-	CH NO Full #	MD6M14	LA4K4P00148	1.0 - 2.0			
Speedometer Assy is		EN NO Full #	AK4PK4500170			1			
damage.		Sale Date #	25/07/20	25/07/2020 Present Kms #			2:		
		Date of Comp#	25/07/20	20 May		Model #	TVS KING		
*			Date of Repair #	25/07/20				Deluxe	
					Free Cupor	n service informa	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN	S	
			1St Free Se	rvice	2nd F	ree Service	3rd Fre	e Service	
			Date	KMs	Date	KiVis	Date	KMs	
7)			25/07/2020	21		X		speedor	
ilread	ly temporary		is defe				ne Jam. Dle not	,	
ilread	ly temporary	repair it. S		e under wa				,	
sL	ly temporary	repair it. S		e under wa Failur	rranty.			,	
	ly temporary	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Nee	lle not	- Notah	
SL	ly temporary Part	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code	lle not	- Notah	
SL 1	ly temporary Part	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code	lle not	- Notah	
SL 1 2 3 4	ly temporary Part	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code	lle not	- Notah	
SL 1 2 3 4 5	ly temporary Part	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code	lle not	- Notah	
SL 1 2 3 4	ly temporary Part	repair it. S	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code	lle not	- Notah	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS	Approved	- Notah	
SL 1 2 3 4 5	ly temporary Part	NO 0150	o It patrs is change	e under wa Failur me	e Particular Qty	Vendor code 1 TVS	lle not	- Notah	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS	Approved	- Notah	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For Hea	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For Hea	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For Hea	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For Hea	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For Hea	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For He	Approved	Rejected	
SL 1 2 3 4 5	ly temporary Part	NO 0150	Part Nai Speedomete	e under wa Failur me	e Particular Qty	Vendor code 1 TVS For He	Approved	Rejected	

Beno