
PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD

DMS NO:



3413

IFAD Tower	Plot-7(New)	Taignan	Industrial	Aroa	Dhaka-1208
II AD TOWEL,	riot-/(ivew),	reiguan	muusmai	Area.	Dnaka-1208

Ref.No:	Dhaka Metro/Jan/12/02	F.R SI NO	02	Date:	12.01.2022	_
Zone Name:	Dhaka Metro	Engineer Nam	ne: MD. Usuf	Mchanic Nan	ne: MD. Usuf	
A server ed b	Variabile Carland (COO ITAD CDOUD)	ULLAN H	AGAAN			

Approved by: Kaush	ik Sarkar (COO IFAD GROUP)	MILON HOSAIN

Customer Name:	Faysal Ahmed			Mobile No:	01620223020		
Address:	Mirpur 10, Dhaka.			Dealer Name:	Satata as Enterprise		
Customer Complain:-		CH NO Full #	MD6N	MD6M14CA1J4L09540/		Present Kms # 11120	
Oil leakage from rear shock absorber		EN NO Full #	AK4LJ4994138 22.12.2020		N/1-1-1-4	TVC VI D. I	
		Sale Date #			Model#	TVS King Deluxe	
		Date of Comp#	03.04.	2021		1St PS Date	
		Date of Repair#					
		Free service information					
		1St Free Serv	rvice 2nd Free Service		3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs
		15.01.2021	1103/	19.02.21	3,312	16.03,2021	5132

Obserbation:- We checked & found that oil leakege Rear shock absorber.

Action Taken:- Require to replace this parts under warranty for your approval.

	Particul	

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	4.
1	G2090100	SHOCK ABSORBER ASSY	. 1	Gabrial			
2							
3					-		N.
4							-

<u>Failure Parts Photo</u>	For Head Office Use					
31.	Head of Service	Engineer	DMS			
	22/1/22	Approved by	Mitisaha 16/01/2022 DMS Complete			