
MOTORSLIMITED

PRODUCT PERFORMANCE FEEDBACK REPORT





DMS NO.

Head Office

<u>IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208</u>						
Ref.No:		F.R SI NO# 05	Date:	9/8/2021		
Zone Name:	Rangpur	Engineer Name:Md:Hosan Ali	Mechanic Name: Bipul			

Approved by: Md:Billal Hossain (Deputy manager Service)

Customer Name:	stomer Name: Ainal			Mobile No:	01757-862674			
Address:	Jaldhaka,Nilphmari			Dealer Name:	Habib Enterprise			
Customer Complain:-		CH NO Full #	MD6M14LA8L4N00004 🗸		Present Kms # 15211			
There is noise inside the engine		EN NO Full #	AK4NL4503759			TVS KING Deluxe plus		
		Sale Date #	23.03.	21	Model #		,	
		Date of Comp#	07.09.21			1St PS Date	1st PS Kms	
		Date of Repair# 08.09.21						
			Free service information					
		1St Free Serv	ee Service 2nd Free Service		3rd Free Service			
		Date	KMs	Date	KMs	Date	KMs	
		25.04.21	980	07 07 21	6 780	07.00.21	15211	

Observation:- There is noise inside the engine

Action Taken:-The engine is poen and Crankshaft connecting loose and cylinder block have scratch.

Failure Particular						
SL	Part NO.	Part Name		vendor code	Approved	Rejected
1	G4322610	Kit cylinder block Piston	01	1	1 1 1 1 1 1 1 1 1	
2	G1020010	Crankshaft Comp	/ 01 /			
3		8	11 3			
4						
-	<u> </u>					

<u>Failure Parts Photo</u>	For Head Office Use					
	Head of Service	Engineer	DMS			
	7000 09/09/2021	Poller 21	Josephal Condite			