PRODUCT PERFORMANCE FEEDBACK REPORT **IFAD MOTORS LTD** DMS NO: **Head Office** 3192 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO#-318 Date: 2/13/2021 Ref.No: Engineer Name: Md Farhad Hossen Mchanic Name: Faruk Zone Name: Chittagong (Kagracori) Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01890857328 Customer Name: | Saifur Rahaman Mobile No: Panchari **Ekota Motors** Address: Dealer Name: CH NO Full # **Customer Complain:-**MD6M14LA5K4P00157 Present Kms # 8592 EN NO Full # Tvs King Deluxe Noise from rear shockabsorber AK4PK4900163 Model# Sale Date # 14-Oct-20 Date of Comp# 13/2/2021 1St PS Date 1st PS Kms Date of Repair# | 13/2/2021 Free service information **1St Free Service** 2nd Free Service **3rd Free Service** ΚMs Date **KMs** Date **KMs** 20/11/20 1025 25/12/20 4,540 Observation:- Rear shockabsorber oil leakage. Action Taken:- New one Rear shockabsorber replace. Failure Particular SL Part NO. Approved Rejected Part Name Qty Vendor code SHOCK ABSORBER ASSY REAR G2090100 Badve 1 1 2 3 4

Head of Service

W182/292

For Head Office Use

Engineer

DMS

Failure Parts Photo