PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO 12.01.2022 04 Date: Ref.No: Dhaka Metro/Jan/12/04 Engineer Name: MD. Usuf Mchanic Name: MD. Usuf **Dhaka Metro** Zone Name: HOSSAN HILON Approved by: Kaushik Sarkar (COO IFAD GROUP) Mobile No: 01716413873 Customer Name: Jahangir Ferdus Satata as Enterprise Address: Keranigonj, Dhaka. Dealer Name: MD6M14CA 9J4L09494 **Customer Complain:-**CH NO Full # Present Kms # 14103 Oil leakage from front shock absorber EN NO Full # AK4LJ4094146 Model# **TVS King Deluxe** Sale Date # 12.02.2021 Date of Comp# 19.06.2021 1St PS Date Date of Repair# Free service information 1St Free Service 2nd Free Service / 3rd Free Service **KMs KMs** Date Date **Date KMs** 20.03.2021 4985 28.01.2021 1203 25.02.21 3,212 Obserbation:- We checked & found that oil leakege front shock absorber. Action Taken:- Require to replace this parts under warranty for your approval. Failure Particular SL Part NO. Vendor code Part Name Qtv Approved Rejected 1 G4100180 Front shock absorber Gabrial 1 2 3 4 Failure Parts Photo For Head Office Use DMS **Head of Service** Engineer Approved by Mail