

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO

			IFAD TOWE	R ,07 Tej	gaon I/A, I	Dhako-1208.		V			
Ref.No: Habigan					F.R SI NO#	306	Date:	16.07.2020			
Zone Name: Habiga			anj Zone		Engineer Name:		Md. Abdullah Al Zabed				
Approved by: Prabir Biswas (Head of Service & Spare Parts)											
Customar Name: Md. Rofikul Ali Mobile No: 01715056309, 01724							01724252647				
			r, Moulvibazar			Dealer Name:	Kaderia Motors				
Customar Complain:-			CH NO Full #	MD6M14CL6K4NA0045		Present Kms #	335				
POOR PICKUP & STARTING PROBLEM			EN NO Full # Sale Date #	OL4NK48A0045 13.07.2020			Model #	TVS KING DURAMAX CNG			
ROBELIVI			Date of Comp#	16.07.2020			1St PS Date	1st PS Kms			
			Date of Repair #								
			Free service information								
ař.			1St Free Service		2nd Free Service		* 3rd Free Service				
			Date	KMs	Date	KMs	Date	KMs			
			16.07.2020	335							
Obserbation:- We checked & found that IGNITION COIL Short: 7 7 7											
Action Taken:- New one IGNITION COIL replaced.											
			\sim								
Failure Particular											
SL	Part I	OV	Part Nan	ne	Qty	Vendor code	Approved	Rejected			
1	G4060		IGNITION COIL			NIG011909A01					
2	(KG/10)	CA260 11				T 010		. 9			

Fallule Falluculai											
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected					
1		IGNITION COIL	$\left(\begin{array}{c}1\end{array}\right)$	NIG011909A01							
2	46,4060250	11		019		- 3					
3.			Amy	me,							
4			U								
5				18							
6		1									

Failure Parts Photo

For Head Office Use

07.09.2020 DHS Complete

Feg | 2020.