

PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD Head Office

DMS no

2269

IFAD TOWER,07 Tejgaon I/A, Dhaka-1208.

Ref.No:	Sep -236	F.R SI NO#	236	Date:	08.08.2020
Zone Name:	Cumilla	En	gineer Name:	Md.Pa	bel Sarker
Approved by:	Prabir Biswas, GM -Head of Service &	Spare Parts.			


Customar Name:	2 1 101			Mobile No:	01701390126		
Address:	Kosba, B.k	paria.	30/21		Dealer Name:	Modina motors	
Customar Cor	mplain:-	CH NO Full #	MD6M14	CAXK4KA006	8	Present Kms #	(2,570)
Front shock Absorber oil		EN NO Full #	AK4KK49	A0068	Model #		Tvs King Deluxe
leakage.		Sale Date #	03.06.202	20	je v	Wiodel#	* lpg
		Date of Comp#	26.08.202	20		1St PS Date	1st PS Kms
		Date of Repair #	26.08.202	20			
Free service information							
		1St Free Sei	1St Free Service 2nd Fr		ee Service	3rd Free Service	
		Date	KMs	Date	KMs	Date	KMs
100 to 95		04.07.2020	980	26.08.2020	2570		

Obserbation:- we checked & found that Front Shock Absorber has oil leakage .

Action Taken:--require to replace front shock absorber by new one under warranty.

Failure Particular							
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected	
1	G2100010	Front Shock Absorber	01	Gabrial			
2		2	X				
3					1	S 1	
4	A					×	
5					1	N 8	
6				1419.5		÷	

Failure Parts Photo For Head Office Use



m182020

14.09.2020

Metubahen 14.09.2020 Drys complete