PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 3249 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Noakhali- May- 246 F.R SI NO 246 Date: 06.05.21 Engineer Name: Kazi Samiul H Mchanic Name: Shipon Mondol Zone Name: Feni-Noakhli Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Customer Name: Rashel Mobile No: 01814068407 Address: Kaliapara, Shahrasti, chadpur. Dealer Name: Bhuiya motors Customer Complain:-CH NO Full # MD6M14CA3K4L00128 Present Km 17000 Engine oil consumption EN NO Full # AK4LK400668 Tvs king duramax Model# Sale Date # 12.07.20 Date of Comp# 06.05.21 1St PS Date 1st PS Kms Date of Repair# 06.05.21 Free service information 1St Free Service 2nd Free Service 3rd Free Service Date **KMs** Date KMs Date **KMs** 18.08.20 1500 19.09.20 3500 24.01.21 9000 Observation:- We checked & found that engine valve kit & piston decay Action Taken:- Please Replaced the following parts under warranty Failure Particular SL Part NO. Part Name Qty Vendor code Approved Rejected 1 G4320670 Piston Kit 1st O/S 4S 8 1 2 G4320780 **ENGINE VALVE KIT** 1 3 4 Failure Parts Photo For Head Office Use Head of Service Engineer DMS the sol To who we have bed

Bis DMS complete