

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD **Head Office**

DMS JC No. 2855

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

| Ref No: | Dhaka 1/Nov'20/017 | F.R SI NO# | 17 | Date: 21.11.2 | 020 |
|------------|--------------------------------|-------------------|------------------|---------------|-----|
| Zone Name: | | Engineer/Sr.M | echanic Name: Yo | ousuf Ali | |
| | Dulin Diamas CM Hand of Coming | Q Cooks Dorte IMI | | | |

| Approved by: | Prabir Bisw | as-Givi, Head of Se | rvice & Sp | are Parts-livit | • | | | |
|------------------------|--------------------------------|-------------------------|-------------|-----------------|--|---------------|-----------------|--|
| | , | | | * ^ * ^ | | T | | |
| Customar Name: | Bashir Ahmed | | | | Mobile No: | 01912-245651 | | |
| Address: | SIRAJDIKHAN, Munshiganj | | | Dealer Name: | Mayer Dowa | | | |
| Customar Com | plain:- | CH NO Full # | MD6M14 | CA9J4L09155 | | | | |
| Customer Complain: Oil | | EN NO Full # | AK4LJ459 | 1971 / | | | | |
| Consumption High. | | Sale Date # | 03.12.202 | 20 | | Present Kms # | / 12966 | |
| | | Date of Comp# | 02.11.202 | 20 | Service of the servic | Model # | TVS KING Deluxe | |
| | | Date of Repair # | | | | Wiodel III | | |
| | Free Cupon service information | | | | | | | |
| * | | 1St Free Service 2nd Fr | | ee Service | 3rd Free Service | | | |
| .e | | Date | KMs | Date | KMs- | Date | KMs | |
| | | 20.01.2020 | 962 | 03.03.2020 | 2477 | 01.06.2020 | 5720 | |
| Obserbation:- We | checked & | found that Valve | Kit excessi | ve Clearance | / | | | |

Action Taken:- Required to replcae parts under warranty replacement for your approval

| Failure Particular | | | | | | | |
|--------------------|----------|----------------|-----|--|----------|----------|--|
| SL | Part NO | Part Name | Qty | Vendor code | Approved | Rejected | |
| 1 | M7010270 | Valve Intake | 1 | 32 Amas | | | |
| 2 | M7010280 | Valve Exhaust | 1 | And the second s | | | |
| 3 | N4011100 | Valve Oil Seal | 2 | region and the state of the sta | | | |
| 4 | | | | CTITOTIC | | 8 | |

Note:Gasket bear by Customer

Failure Parts Photo

For Head Office Use

ic Norma

Now

Ons Complete

SAFER (Displication