PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3242 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 23 Date: 08.05.2021 F.R SI NO# Ref.No: Dhaka/April/23 Mchanic Name: Md.Yousuf Engineer Name: Milon Hossain Zone Name: Dhaka 1 Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01610-498798 Mobile No: Md.Faisal **Customer Name:** Satat As Center **Dealer Name:** Uttara, Dhaka Address: MD6M14CAJ4L09540 Present Kms 4309 CH NO Full # **Customer Complain:-**AK4LJ4994138 EN NO Full # Steering Column Broken TVS King Deluxe Model# Sale Date # 02.01.2021 1St PS Date 1st PS Kms 07.05.2021 Date of Comp# Date of Repair# Free service information **3rd Free Service** 2nd Free Service **1St Free Service KMs Date** KMs Date **KMs Date** 2,608 906 04.04.2021 05.03.2021 Observation:we checked &found that Steering Column Broken. Action Taken:- Require to replace this parts under warranty for approval. Failure Particular Vendor code Approved Rejected Qty Part Name Part NO. SL STEERING COLUMN 1 G2150010 1 **PIVOT PIN FRONT KIT** 1 G5320470 2 3 4 5 For Head Office Use **Failure Parts Photo DMS Head of Service Engineer** Syrappin Straight