PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3271 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 19.05.2021 F.R SI NO# Date: Ref.No: Dhaka/May/27 Mchanic Name: Md.Yousuf Engineer Name: Milon Hossain Zone Name: Dhaka 1 Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01610-498798 Mobile No: Md.Syed ahmed Rasel Customer Name: Satata As Center Dealer Name: Mirpur, Dhaka Address: 5754 MD6M14CA1J4L09506 Present Kms CH NO Full # Customer Complain:-AK4L14694132 EN NO Full # Front & Rear Shockabsorber Oil **TVS King Deluxe** Model# 05.01.2021 Sale Date # Leakage 1st PS Kms 1St PS Date 17.05.2021 Date of Comp# Date of Repair# Free service information **3rd Free Service** 2nd Free Service 1St Free Service **KMs** Date KMs. Date **KMs** Date 4798 28.04.2021 2.890 28.03.2021 987 19.02.2021 Observation:we checked &found that front & Rear Shockabsorber oil Leakage . . Action Taken:- Require to replace this parts under warranty for your kind approval. Failure Particular Approved Rejected Vendor code Qty Part Name Part NO. SL 1 , SHOCK ABSORBER FRONT G4100180 1 1 SHOCK ABSORBER ASSY REAR G2090100 2 3 4 5

Failure Parts Photo	For Head Office Use		
randierandimoto	Head of Service	Engineer	DMS
			on bloke
	805 W 5 1000	23/05/2021	Carlos Carlos
	. Jan	o o	See