PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Noakhali/Cumilla- Dec - 256 F.R SI N 256 Date: Zone Name: Feni-Noakhali- Cumilla Engineer: Kazi Samiul Hoque Mchanic Name: Sumon dali Approved by: Kaushik Sharkar, COO-IFAD GROUP **Customer Name:** Jasmin Akter Mobile No: 01839356437 Address: Bolakhal,hajigonj,chadpur **Dealer Name:** Shikder Enterprise **Customer Complain:-**CH NO Full # MD6M14CL0K4P00049 Present Km **Engine oil consumption** EN NO Full # 0L4PK4100322 Model#

Sale Date #

Date of Comp#

Date of Repair#

DMS NO:

26.12.21

*3*408

20000

Tvs king duramax

1st PS Kms

1St PS Date

Free service information

	1St Free Sei	1St Free Service		2nd Free Service		3rd Free Service	
	Date	KMs	Date	KMs	Date	KMs	
	16.03.21	8000	21.07.21	15000			
Ob				100 01 170 070			

1St Free Service

Observation:- We checked & found that Piston ring (kit) decay.

Action Taken:- Please Replaced the following parts under warranty

Failure Particular							
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Paiastad	
1	G4020130	PISTON 66.00	1	- Cildor code	Approved	Rejected	
2	G4011350	Gasket Cyl Head	1				
3			+				
4							
						}	

09.11.20

23.12.21

25.12.21

Failure Parts Photo	For Head Office Use				
1	Head of Service	Engineer	DMS		
	29/12/	Approved by Mail	11. 0 1		
* * * * * * * * * * * * * * * * * * * *			Durcumax		