Ref.No Zone Name Approved by Customer Name:

PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

Head Office

DMS NO:

3218

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No:	Sylhet/Mar/21/300	F.R SI NO	300	Date:	21.03.2021	
Zone Name: Sylhet Sadar		Engineer Name: Tisu Barua		Mchanic Name: Md. Delower Hossain		

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name:	Parbin Begum			Mobile No:	01728987307		
Address:	Companygonj, Sylhet.	Dealer Name:			Shaporan Motors		
Customer Complain:-		CH NO Full #	MD6M14CA6K4L00141/		Present Km	14,784	
Oil leakege from rear shock absorber		EN NO Full #	AK4LK4X06770			Model #	TVS King Deluxe
		Sale Date #	13.09.2020				
		Date of Comp#	25.02.2021		1St PS Date	1st PS Kms	
		Date of Repair#	. ~				· · · · · · · · · · · · · · · · · · ·
		Free service information					
		1St Free Service 2nd F		ree Service	3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs
		11.10.2020	965/	12.11.20	3,986	09.12.20	7912

Obserbation:- We checked & found that oil leakege from left side rear shock absorber.

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular

SL	Part NO.	Part Name	Qty/	Vendor code	Approved	Rejected	125
1	G2090100	SHOCK ABSORBER ASSY	000	Gabrial			
2		4	Ÿ.	0	22		8
3		/					4
4	4.1						

Failure Parts Photo	For Head Office Use				
	Head of Service	Engineer	DMS		
	27(3/2021	A Cal Land	Har Company		