

Each exact P–D slice passes through both reference points. Purple marks identify the failure-flight gains; Z gains coincide.

Each case uses its own posterior. Other controller gains are fixed at the successful-flight values.