

failure2: sensor reconstruction from first-order + external-wrench replay

gyro RMSE [0.0245 0.0322 0.0252]

specific-force RMSE [0.3579 0.0946 0.0857]

