


Each exact P-D slice passes through the recorded failure point. Purple: failure gains; blue: successful gains.

Success rates: all 12 gains set to successful values; background: other 9 at failure values. All original samples retained.