


Each exact P-D slice passes through the recorded failure point. Purple marks identify the failure-flight gains.

Each case uses all original plant samples; other nine gains are fixed to that failure record.