


Each exact P-D slice passes through the recorded failure point. Purple: failure gains; blue: successful gain coordinates only.

Each case uses all original plant samples; other nine gains are fixed to that failure record.