

180
90
0
Pressure P(t) [bar]
Stroke End (P₀)
High Density (Heavy Mass)
Slow plastic decay (Dense waste)
Forward Work Area
Total Stroke Energy
Low Density (Light / Hollow)
Fast elastic rebound (Springy waste)
Piston Stroke & Decompression Time t [s]
← Pressure Rebound Window →