


Figure 4. Best-method fault-bus confusion matrix under unseen 10Ω resistance

IEEE14 best proposed



IEEE30 best proposed

