



#### **Outline**


- 1. Introduction
- 2. Defining the Root Locus
- 3. Properties of the Root Locus
- 4. Sketching the Root Locus (K > 0)
  - 1. Rules of Sketching the Root Locus
  - 2. Summary of the Procedure for Sketching the Root Locus
- General Form of Root Locus
- 6. Transient Response Design via Gain Adjustment



#### 8.1 Introduction

Root locus, a graphical presentation of the closed-loop poles as a system parameter is varied, is a powerful method of analysis and design for stability and transient response (*Evans*, 1948, 1950).

The root locus can be used to describe qualitatively the performance of a system as various parameters are changed.



Walter Richard Evans



Forward transfer

function

KG(s)

H(s)

Feedback transfer function

Actuating

signal


 $E_a(s)$ 

Input

R(s)

#### Introduction(cont'd):

- System performance and stability → determined by closed-loop poles
- Typical closed-loop feedback control system



$$G(s) = \frac{(s+1)}{s(s+2)}$$
  $H(s) = \frac{(s+3)}{(s+4)}$ 

FIGURE 8.1

Output

C(s)

#### Open-loop TF

$$KG(s)H(s) = \frac{K(s+1)(s+3)}{s(s+2)(s+4)}$$

Zeros 
$$\rightarrow$$
 -1, -3  
Poles  $\rightarrow$  0, -2, -4

- Location of poles → easily found
- •Variation of gain  $K \rightarrow do$  not affect the location of any poles

#### Closed-loop TF

$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)}$$
$$= \frac{K(s+1)(s+4)}{s^3 + (6+K)s^2 + (8+4K)s + 3K}$$

- Location of poles → need to factor the denominator
   → difficult
- •variation of gain K → do change the location of poles

```
for k = 0:10
    p = [1,6+k, 8+4*k,3*k];
    r = roots(p);
    plot(k, r, 'k*');
    hold on
end
hold off
```

- Easy way to know the CL pole locations w/o solving higher-order characteristic equation of CLTF for various gain K?
- Root locus
  - graphical representation of the closed-loop poles as a function of system parameters
  - Can be used to design system parameters of the high order systems to yield a desired system specifications
  - Estimating closed-loop poles' location when gain K is varied using open-loop poles
  - Represent the poles of T(s) as K varies



#### Open-loop TF


## $KG(s)H(s) = \frac{K(s+1)}{s(s+2)} \frac{(s+3)}{(s+4)}$


#### Closed-loop TF


$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)} = \frac{K(s+1)(s+4)}{s^3 + (6+K)s^2 + (8+4K)s + 3K}$$

$$=K\frac{N(s)}{D(s)}.$$

```
p = conv(conv([1 0],[1 2]),[1 4])
r = roots(p);
scatter(real(r),imag(r),'k*')
```









## 8.2. Defining the Root Locus

#### Camera Example

- System below can automatically track subject wearing infrared sensors.
- Solving for the poles using the quadratic equation, we can create the table below for different values of K.




Table 8.1 of [Nise, 2015]. The effect of gain  $K = K1K2 \ge 0$  on the placement of the system's poles.




Figure 8.4 (a): Camera with 1 degree of freedom (pitch angle) [Nise, 2015].




Figure 8.4(b)-(c): (b) Block diagram of the camera system; and (c) equivalent diagram. [Nise, 2015].





Figure 3: (a) Pole placements for different values of K > 0; and (b) root locus. Figure 8.5 of [Nise, 2015].



#### Type 1 system (no disturbance)



Closed-loop transfer function


$$\frac{X(s)}{V_{ref}(s)} = \frac{0.3162K}{s^2 + 2s + 0.3162K}$$

Pole locations

$$p_1 = -1 + \sqrt{1 - 0.3162K}$$
  $p_2 = -1 - \sqrt{1 - 0.3162K}$ 

System becomes **underdamped**⇒
⇒ step response **overshoots** if

$$1 - 0.3162K < 0 \Leftrightarrow K > 3.1626$$






## Vector Representation of Complex Number

What is complex number?

$$s = \sigma + j\omega$$

Complex number is a vector



Vector has magnitude and direction

$$s = \sigma + j\omega$$

Therefore, we can also represent complex number s as:

$$M = \sqrt{\sigma^2 + \omega^2}$$
$$\theta = \tan^{-1} \left(\frac{\omega}{\sigma}\right)$$



## Vector Representation of Complex Number

But, if s is a variable in a function, how to represent the complex number. For example,  $S = M / \Omega$ 


$$s = M \angle \theta$$

Replacing s,

$$F(s) = s + a$$

Another complex number

## Graphically,







## Vector Representation of Complex Number

$$F(s) = \frac{M \angle \theta}{\prod_{i=1}^{m} (s + z_i)}$$

$$M = \frac{\prod_{i=1}^{m} \operatorname{cero length}}{\prod_{i=1}^{m} \operatorname{cero length}} = \frac{\prod_{i=1}^{m} |(s + z_i)|}{\prod_{j=1}^{n} |(s + p_j)|}$$

$$\theta = \sum_{i=1}^{m} \operatorname{cero length} = \frac{\prod_{i=1}^{m} |(s + p_i)|}{\prod_{j=1}^{n} |(s + p_j)|}$$

$$\theta = \sum_{i=1}^{m} \operatorname{cero length} = \frac{\prod_{i=1}^{m} |(s + p_i)|}{\prod_{j=1}^{n} |(s + p_j)|}$$

$$\theta = \sum_{i=1}^{m} \operatorname{cero length} = \frac{\prod_{i=1}^{m} |(s + p_i)|}{\prod_{j=1}^{n} |(s + p_j)|}$$

$$\theta = \sum_{i=1}^{m} \operatorname{cero length} = \frac{\prod_{i=1}^{m} |(s + p_i)|}{\prod_{j=1}^{n} |(s + p_j)|}$$



# Vector Representation of Complex Number Example


$$F(s) = \frac{s+1}{s(s+2)}$$

$$s = -3 + j4$$

## What is F(s)?


$$F(s) = \frac{\sqrt{20}}{5\sqrt{17}} \angle \left(116.6^{\circ} - 126.9^{\circ} - 104.0^{\circ}\right)$$

$$F(s) = 0.217 \angle -114.3^{\circ}$$





## Root locus terminology





### 8.3 Properties of the root locus

■ FB CL poles, [1, p. 388]

The unknown parameter k affects the location of poles and therefore the response of the system to an input.

$$\begin{array}{c|c}
R(s) & \hline \\
\hline s(s+k)+1 & Y(s)
\end{array}$$

What value of k should I choose to meet my system performance requirements? If the value of k is exactly as predicted, what is the effect of a variation of k on my system?

Brute-force method:



#### Open-loop transfer function (OLTF)

Consider the closed-loop system in Fig. 4. The OLTF is KG(s)H(s).

$$T(s) = \frac{KG(s)}{1 + KG(s)H(s)}$$

The angle of the complex number is an odd multiple of  $180^{\circ}$ 

$$KG(s)H(s) = -1 = 1\angle(2k+1)180^{\circ}$$
  
 $k = 0, \pm 1, \pm 2, \pm 3, \dots$ 

R(s) + R(s) R(s) R(s) R(s)

Figure: -FB system

The system gain, K, satisfies magnitude criterion

$$|KG(s)H(s)| = 1$$

angle criterion

$$\angle KG(s)H(s) = (2k+1)180^{\circ}$$

and thus

$$K = \frac{1}{|G(s)||H(s)|}$$

Figure 4: (a) Closed-loop system; and (b) equivalent transfer function. Figure 8.1 of [Nise, 2015].

- Let the OLTF be of the form OLTF  $\equiv K \frac{N(s)}{D(s)}$ .
- Then, the system's closed-loop system's characteristic equation is in the form of :

$$1 + \text{OLTF} = 1 + K \frac{N(s)}{D(s)} = 1 + K \frac{(s - z_1)(s - z_2) \cdots (s - z_m)}{(s - p_1)(s - p_2) \cdots (s - p_n)} = 0,$$

$$\Rightarrow \frac{(s - z_1)(s - z_2) \cdots (s - z_m)}{(s - p_1)(s - p_2) \cdots (s - p_n)} = -\frac{1}{K}$$

Any point on the RL must satisfy two conditions (amplitude condition and phase condition):

$$\frac{\prod_{i=1}^{m} |(s-z_i)|}{\prod_{i=1}^{n} |(s-p_i)|} = \left| -\frac{1}{K} \right| \tag{1}$$

ii. 
$$\sum_{i=1}^{m} \frac{/(s-z_i)}{-\sum_{i=1}^{n} \frac{/(s-p_i)}{-\sum_{i=1}^{n} \frac{/$$

## Root Locus (K > 0)

■ When K > 0 the amplitude and phase conditions become :

i. 
$$\frac{\prod_{i=1}^{m} |(s-z_i)|}{\prod_{i=1}^{n} |(s-p_i)|} = \left| -\frac{1}{K} \right| = \frac{1}{K}$$

ii. 
$$\sum_{i=1}^{m} \frac{\sqrt{(s-z_i)} - \sum_{i=1}^{n} \sqrt{(s-p_i)}}{\sum_{i=1}^{n} \sqrt{(s-p_i)}} = \frac{\sqrt{-\frac{1}{K}}}{\sum_{i=1}^{m} (2q+1)180^{\circ}}; \quad q = 0, \pm 1, \pm 2, \dots$$

## 8.4 sketching -FB RL, [1, p. 390]

#### Basic 5-rules to sketch a root locus rapidly.

- 1-Number of branches (Number of Loci): Equals the number of CL poles
- 2-Symmetry: About the real axis
- 3-Real-axis segments: On the real axis, for K >0, the RL exists to the left of an odd number of real-axis, finite OL poles and/or finite OL zeros
- 4-Starting and ending points: The RL begins at the finite & infinite poles of G(s)H(s) and ends at the finite & infinite zeros of G(s)H(s).
- 5-Behavior at  $\infty$ : The RL approaches straight lines as asymptotes as the RL approaches  $\infty$ . Further, the equation of the asymptotes is given by the real-axis intercept,  $\sigma_a$ , and angle,  $\theta_a$ , as follows,

$$\sigma_a = \frac{\sum \text{finite poles} - \sum \text{finite zeros}}{\# \text{finite poles} - \# \text{finite zeros}}$$

$$\theta_a = \frac{(2k+1)\pi}{\# \text{ finite poles} - \# \text{ finite zeros}}$$

where k = 0;  $\pm 1$ ;  $\pm 2$ ;  $\pm 3$  and the angle is given in radians with respect to the positive extension of the real axis.



#### Example 8.2

#### **Sketching a Root Locus with Asymptotes**

**PROBLEM:** Sketch the root locus for the system shown in Figure 8.11.




FIGURE 8.11 System for Example 8.2

Basic rules

1-Number of branches

**SOLUTION**: Let us begin by calculating the asymptotes.

OLTF 
$$\equiv K \frac{N(s)}{D(s)}$$
. Poles={0,-1,-2,-4} & zeros={-3}

4-Starting and ending points 5-Behavior at ∞

 $\forall s \in (0, \infty), = 0 \text{ (even)} \Rightarrow (0, \infty) \notin RL.$  $\forall s \in (-1, 0), = 1 \text{ (odd)} \Rightarrow (-1, 0) \in RL.$  $\forall s \in (-2,-1),=2 \text{ (even)} \Rightarrow (-2,-1) \notin RL.$  $\forall s \in (-3, -2), = 3 \text{ (odd)} \Rightarrow (-3, -2) \in RL.$  $\forall s \in (-4,-3), = 4 \text{ (even)} \Rightarrow (-4,-3) \notin RL.$ 

 $\forall s \in (-\infty, -4), = 5 \text{ (odd)} \Rightarrow (-\infty, -4) \in RL.$ 

The real-axis segments lie to the left of an odd number of poles and/or zeros.





- The locus starts at the open-loop poles and ends at the open-loop zeros.
- There are more open-loop poles than open-loop zeros.
   Thus, there must be zeros at infinity. The asymptotes tell us how we get to these zeros at infinity.

1-Number of branches	
2-Symmetry	Ī
3-Real-axis segments	
4-Starting and ending point	S
5-Behavior at ∞	

$$\sigma_a = \frac{\sum \text{finite poles} - \sum \text{finite zeros}}{\# \text{finite poles} - \# \text{finite zeros}}$$

$$\sigma_a = \frac{(-1-2-4)-(-3)}{4-1} = -\frac{4}{3}$$


$$\theta_a = \frac{(2k+1)\pi}{\text{# finite poles} - \text{# finite zeros}}$$

$$= \pi/3 \qquad \text{for } k = 0$$

$$= \pi \qquad \text{for } k = 1$$

$$= 5\pi/3 \qquad \text{for } k = 2$$

If the value for k continued to increase, the angles would begin to repeat. The number of lines obtained equals the difference between the number of finite poles and the number of finite zeros.  $\theta_a = \pi/3$  for k = 3



In this example, poles = 
$$\{0, -1, -2, -4\}$$
,  
zeros =  $\{-3\}$  so

$$\sigma_a = \frac{[0 + (-1) + (-2) + (-4)] - [(-3)]}{4 - 1} = -\frac{4}{3}$$

$$\theta_a = \frac{(2m+1)\pi}{4-1} = \left\{\frac{\pi}{3}, \pi, \frac{5\pi}{3}\right\}$$



## 8.5 Refining the Sketch -FB RL, [1, p. 395]

#### Additional rules for refining a RL sketch

- 6-Real-axis breakaway & break-in points: At the breakaway or break-in point, the branches of the RL form an angle of 180/n with the real axis, where n is the number of CL poles arriving at or departing from the single breakaway or break-in point on the real-axis.
- **7-The** j $\omega$ -axis crossings: The j $\omega$ -crossing is a point on the RL that separates the stable operation of the system from the unstable operation.
- **8-Angles of departure & arrival:** The value of  $\omega$  at the axis crossing yields the frequency of oscillation, while the gain, K, at the j $\omega$ -axis crossing yields the maximum or minimum positive gain for system stability.
- 9-Plotting & calibrating the RL: All points on the RL satisfy the angle criterion, which can be used to solve for the gain, K, at any point on the RL.

## Rule6 (a) Breakaway and Break-in Points via Differentiation

6-Break in/out point
7-jω-axis crossings
8-Angles of dep& arriv
9-9-Plotting & calibrating

- Procedure
- Maximize & minimize the gain, K, using differential calculus: The RL breaks away from the real-axis at a point where the gain is maximum and breaks into the realaxis at a point where the gain is minimum. For all points on the RL


$$K = -\frac{1}{G(s)H(s)}$$

For points along the real-axis segment of the RL where breakaway and break-in points could exist,  $s = \sigma$ . Differentiating with respect to  $\sigma$  and setting the derivative equal to zero, results in points of maximum and minimum gain and hence the breakaway and break-in points.

#### Example 8.3

#### **Breakaway and Break-in Points via Differentiation**

**PROBLEM:** Find the breakaway and break-in points for the root locus of Figure 8.13, using differential calculus.



#### Example 8.3

#### **Breakaway and Break-in Points via Differentiation**

**PROBLEM:** Find the breakaway and break-in points for the root locus of Figure 8.13, using differential calculus.

**SOLUTION:** Using the open-loop poles and zeros, we represent the open-loop system whose root locus is shown in Figure 8.13 as follows:

$$KG(s)H(s) = \frac{K(s-3)(s-5)}{(s+1)(s+2)} = \frac{K(s^2 - 8s + 15)}{(s^2 + 3s + 2)}$$
(8.33)

But for all points along the root locus, KG(s)H(s) = -1, and along the real axis,  $s = \sigma$ . Hence,

$$\frac{K(\sigma^2 - 8\sigma + 15)}{(\sigma^2 + 3\sigma + 2)} = -1 \tag{8.34}$$

Solving for K, we find

$$K = \frac{-(\sigma^2 + 3\sigma + 2)}{(\sigma^2 - 8\sigma + 15)} \tag{8.35}$$

Differentiating K with respect to  $\sigma$  and setting the derivative equal to zero yields

$$\frac{dK}{d\sigma} = \frac{(11\sigma^2 - 26\sigma - 61)}{(\sigma^2 - 8\sigma + 15)^2} = 0$$
(8.36)

$$11x^2 - 26x - 61 = 0$$

Solve for x



Solve the equation for x by finding a, b, and c of the quadratic then applying the quadratic formula.

Exact Form:

$$x=\frac{13+2\sqrt{210}}{11},\frac{13-2\sqrt{210}}{11}$$

Decimal Form:

$$x = 3.81661395..., -1.45297759...$$

Solving for  $\sigma$ , we find  $\sigma = -1.45$  and 3.82, which are the breakaway and break-in points.

## Rule6. (b) Breakaway and Break-in Points via Transition procedure

6-Break in/out point
7-jω-axis crossings
8-Angles of dep& arriv
9-9-Plotting & calibrating

#### Procedure

■ Eliminates the need to differentiate. Breakaway and break-in points satisfy the relationship

$$\sum_{1}^{m} \frac{1}{\sigma + z_i} = \sum_{1}^{n} \frac{1}{\sigma + p_i}$$

where zi and pi are the negative of the zero and pole values, respectively, of G(s)H(s).

#### Example 8.4

#### **Breakaway and Break-in Points Without Differentiation**

**PROBLEM:** Repeat Example 8.3 without differentiating.

**SOLUTION:** Using Eq. (8.37),

$$\frac{1}{\sigma - 3} + \frac{1}{\sigma - 5} = \frac{1}{\sigma + 1} + \frac{1}{\sigma + 2} \tag{8.38}$$

Simplifying,

$$11\sigma^2 - 26\sigma - 61 = 0 \tag{8.39}$$

Hence,  $\sigma = -1.45$  and 3.82, which agrees with Example 8.3.

$$\frac{1}{x-3} + \frac{1}{x-5} = \frac{1}{x+1} + \frac{1}{x+2}$$

Solve for x



Solve the rational equation by combining expressions and isolating the variable  $oldsymbol{x}$ .

Exact Form:

$$x = \frac{13 + 2\sqrt{210}}{11}, \frac{13 - 2\sqrt{210}}{11}$$

Decimal Form:

$$x = 3.81661395..., -1.45297759...$$



## Rule7. The j $\omega$ -crossings, [1, p. 399]

#### Procedures for finding j $\omega$ -crossings




- Using the Routh-Hurwitz criterion, forcing a row of zeros in the Routh table will yield the gain; going back one row to the even polynomial equation and solving for the roots yields the frequency at the imaginaryaxis crossing.
- At the j $\omega$ -crossing, the sum of angles from the finite OL poles & zeros must add to (2k + 1)180



## Example 8.5-Frequency and Gain at Imaginary-Axis Crossing



PROBLEM: For the system of Figure 8.11, find the frequency and gain, *K*, for which the root locus crosses the imaginary axis. For what range of *K* is the system stable?




**SOLUTION**: The closed-loop transfer function for the system

$$T(s) = \frac{K(s+3)}{s^4 + 7s^3 + 14s^2 + (8+K)s + 3K}$$



A complete row of zeros yields the possibility for imaginary axis roots. For positive values of gain, those for which the root locus is plotted, only the s1 row can yield a row of zeros. Thus,



K has two numbers, but we need positive as, K = 9.65

Forming the even polynomial by using the s2 row with K = 9.65, we obtain  $(90 - k)s^2 + 21k = 80.35s^2 + 202.7 = 0$ 

s is found to be equal to  $\pm j1.59$ .





# Rule8. Angles of departure & arrival, [1, p. 400]

Consider the following two systems

6-Break in/out point
7-jω-axis crossings
8-Angles of dep& arriv

9-9-Plotting & calibrating





Similar systems, with very different stability behavior
Understanding how to determine angles of departure from complex poles and angles of arrival at complex zeros will allow us to predict this

#### Angle of Departure

- $\square$  To find the angle of departure from a pole,  $p_1$ :
  - $\square$  Consider a test point,  $s_0$ , very close to  $p_1$
  - The angle from  $p_1$  to  $s_0$  is  $\phi_1$
  - The angle from all other poles/zeros,  $\phi_i/\psi_i$ , to  $s_0$  are approximated as the angle from  $p_i$  or  $z_i$  to  $p_1$
  - $lue{}$  Apply the angle criterion to find  $\phi_1$

$$\sum_{i=1}^{m} \psi_i - \phi_1 - \sum_{i=2}^{n} \phi_i = (2i+1)180^{\circ}$$

□ Solving for the departure angle,  $\phi_1$ :

$$\phi_1 = \sum_{i=1}^{m} \psi_i - \sum_{i=2}^{n} \phi_i - 180^{\circ}$$

In words:

$$\phi_{depart} = \Sigma \angle (zeros) - \Sigma \angle (other poles) - 180^{\circ}$$


### Angles of departure & arrival, example

The RL departs from complex, OL poles and arrives at complex, OL zeros

#### Example 8.6

#### **Angle of Departure from a Complex Pole**

**PROBLEM:** Given the unity feedback system of Figure 8.16, find the angle of departure from the complex poles and sketch the root locus.



**FIGURE 8.16** Unity feedback system with complex poles


**Departure**: from complex poles.

**Arrival**: to complex zeros.



Angle of departure: Zero: -2 Poles:-3, -1+j, -1-j

we calculate the sum of angles drawn to a point close to the complex pole, -1 + j



Sum (zero angles) – Sum (pole angles) =  $(2k+1)180^{\circ}$ 

$$-\theta_1 - \theta_2 + \theta_3 - \theta_4$$

$$= -\theta_1 - 90^\circ + \tan^{-1} \left(\frac{1}{1}\right) - \tan^{-1} \left(\frac{1}{2}\right) = 180^\circ$$

from which  $\theta = -251.6^{\circ} = 108.4^{\circ}$ .

A sketch of the root locus is shown in Figure 8.17.

Notice how the departure angle from the complex poles helps us to refine the shape.



### Procedure for Sketching the Root Locus

- 1. Obtain the system's characteristic equation and write it in the form of 1 + KGH(s) = 0, where K is the parameter of interest. Then, determine the poles and zeros of the OLTF KGH(s).
- 2. Position the poles and zeros of the OLTF on the s-plane and mark them with 'x' and 'o', respectively.
- 3. Draw the segments of the RL on the real axis.
- 4. Determine the location of the break-in and break-away points on the real axis, if any.
- Calculate the points of intersection with the imaginary axis (critical frequency), if any.
- Compute the angles of departure from complex poles and the angles of arrival to complex zeros, if any.
- 7. Determine the number of asymptotic directions.
- 8. Determine the angles of the asymptotes and their intersection point on the real axis.








Problem1. Consider the following system, where

$$G_c(s) = \frac{K}{s}$$
,  $H(s) = (s+3)$ ,  $G(s) = \frac{1}{(s+2)(s^2+2s+2)}$ , and  $K > 0$ 



Sketch the root locus of this system, as precisely as possible, as K varies in the interval  $(0, \infty)$ .



#### 1-Number of branches

2-Symmetry

3-Real-axis segments

4-Starting and ending points

5-Behavior at ∞

A locus (branch) is the virtual path of one pole of the closed-loop system on the *s* plane.

$$1 + k \frac{s+3}{s(s+2)(s^2+2s+2)} = 1 + OLTF \equiv 1 + K \frac{N(s)}{D(s)} = 0 \text{ (right form)}$$

The number of loci is :  $max\{n, m\} = 4$ 

one zero, 
$$z_1 = -3$$
  $(m = 1)$ , and

four poles, 
$$p_1 = 0$$
,  $p_2 = -2$ ,  $p_{3,4} = -1 \pm j$   $(n = 4)$ 

1-Number of branches

#### 2-Symmetry

3-Real-axis segments


4-Starting and ending points


5-Behavior at ∞

The complex roots of the characteristic equation are in the form of conjugate pairs.


Non-Real-Axis Root-Locus Segments








Hitham Jleed




In general: The branches start at the open-loop poles and end at the open-loop zeros.



40






If n > m, (n - m) branches of the root locus take asymptotic directions as  $K \to \infty$ .

- $\triangleright$  Number of asymptotic branches : n-m
- All asymptotes intersect at a single point  $\sigma_a$  on the real axis:  $\nabla^n = \nabla^m = \nabla^m$

$$\sigma_a = \frac{\sum_{i=1}^n p_i - \sum_{i=1}^m z_i}{n-m}$$

$$\sigma_d = \frac{-2-1-j-1+j+3}{4-1} = -\frac{1}{3}$$



> Angles of asymptotes :

$$\theta_a = \frac{(2q+1)180^{\circ}}{(n-m)}, \ q = 0, \pm 1, \pm 2, \dots$$



6-Break in/out point

7-j $\omega$ -axis crossings

8-Angles of dep& arriv

9-9-Plotting & calibrating

dk $\overline{d\sigma}$  $\overline{\sigma(\sigma+2)(\sigma^2+2\sigma+2)}$ 



Graph each side of the equation.

 $\sigma \approx -3.64872899, -1.53909438$ 

6-Break in/out point

7-j $\omega$ -axis crossings

8-Angles of dep& arriv

9-9-Plotting & calibrating

$$\frac{20 - k}{4}s^2 + 3k = 0$$

$$S = \pm \sqrt{1.55}$$

$$T(s) = \frac{k}{s^4 + 4s^3 + 6s^2 + (4+k)s + 3k}$$

 $s^4$ 

 $s^3$ 

 $s^2$ 

S

 $-k^2 - 32k + 20$  $\frac{1}{20 - k}$ 

(20-k)/4

4+k


3k



3k

$$-k^2 - 32k + 20 = 0$$

K = 2.3 or -34.32 So we choose the positie




6-Break in/out point

7-j $\omega$ -axis crossings

8-Angles of dep& arriv


9-9-Plotting & calibrating


$$\theta = \tan^{-1}(\frac{1}{2}) - 90 - \tan^{-1}\left(\frac{1}{1}\right) - \left(180 - \tan^{-1}\left(\frac{1}{1}\right)\right) - 180$$





### Verification: Figures 6 and 7 confirm the validity of the manually-drawn root locus.







## Verification (cont'd)





Figure 7: Unit step responses with various gains (showing system stability).



K = 2.33 (marginally stable)



**Problem 2.** For each of the following OPLTF, sketch the root loci for the system. Find for each the (i) number of branches in the root locus, (ii) number of asymptotes, and give the angles and centers, (iii) the break-in or break-away points, if any, and (iv) angles of departure from poles above the real axis.


(a) 
$$\frac{s-1}{(s^2+4)(s+3)}$$

(b) 
$$\frac{1}{s^2 + 3}$$


$$\frac{s-1}{(s^2+4)(s+3)}$$
 (b)  $\frac{1}{s^2+3}$  (c)  $\frac{(s+4)(s+3)}{(s+5)(s+8)}$ 




(a) Poles= 
$$\{-3, \pm j2\}$$
, zeroes= $\{1\}$ 



- (ii) 2 asymptotes,  $\theta = \frac{\pi}{2}, \frac{3\pi}{2}, centered \ at -2$
- (iii) no break-in/break-away points





(shown for gain between 0 and 10)

The sum of the angles from all poles and zeros to a point near the complex pole must add up to odd multiples of  $\pi$ .  $(180^{\circ} - \tan^{-1}(2/1)) - 90^{\circ} - \tan^{-1}(2/3) - \theta = 180^{\circ}$  so  $\theta = -187.1^{\circ} = 172.9^{\circ} \pmod{180^{\circ}}$ .

Hitham Jleed

46




(b) 
$$\frac{1}{s^2 + 3}$$


Poles=
$$\{\pm j\sqrt{3}\}$$

- (i) 2 branches
- (ii) 2 asymptotes,  $\theta = \frac{\pi}{2}, \frac{3\pi}{2}$ , centered at 0
- (iii) no break-in/break-away points
- (iv) angle of departure from pole at  $s = \sqrt{3}i$  is  $90^{\circ}$   $-90^{\circ} \theta = 180^{\circ}$  so  $\theta = -270^{\circ} = 90^{\circ}$  (mod  $180^{\circ}$ ).

(c) 
$$\frac{(s+4)(s+3)}{(s+5)(s+8)}$$



- (ii) no asymptotes
- (iii) break-away at s=-5.72, break-in at s=-3.61Break-away occurs when  $K(\sigma)=-\frac{1}{G(\sigma)}=-\frac{(s+5)(s+8)}{(s+4)(s+3)}$  is maximum, that is when  $\frac{\mathrm{d}K}{\mathrm{d}\sigma}=0$ .
- (iv) no departure from complex poles



### Problem 8 chapter8 [Nise, p 425]

8. The characteristic polynomial of a feedback control system, which is the denominator of the closed-loop transfer function, is given by  $s^3 + 2s^2 + (20K + 7)s + 100K$ . Sketch the root locus for this system. [Section: 8.8]

#### Solution

$$s^3 + 2s^2 + (20K + 7)s + 100K = 0$$

When this CE is put into "root locus" for versus parameter K, it is

$$1 + K \frac{20(s+5)}{s \underbrace{(s^2 + 2s + 7)}_{s+1 \pm j2.45}} = 0$$

Real-axis branches. As shown on the sketch, there is a real axis branch between the pole at s = 0 and the zero at s = -5.

Asymptote intersection and angle. Since there are 3 poles and 1 zero, there are 2 asymptotes. The asymptote angle and intersection are:

$$\theta_a = \frac{\pm 180^{\circ}}{3-1} = \pm 90^{\circ}, \quad \sigma_a = \frac{-1-1-(-5)}{3-1} = \frac{3}{2} = 1.5$$

Imaginary axis crossing point and corresponding K. Substituting  $s = j\omega$  into the characteristic equation

$$j\omega(-\omega^2 + j2\omega + 7) + K[20(j\omega + 5)] = 0.$$

so

$$j\omega^{3} - 2\omega^{2} + j7\omega + j20K\omega + 100K = 0.$$

yields a Real equation and an Imag equation:

Real: 
$$-2\omega^2 + 100K = 0$$


Imag: 
$$-\omega^3 + 7\omega + 20K\omega = 0$$


simultaneously (not hard), you find that

$$K = \frac{7}{30} = 0.2333, \quad \omega = \sqrt{50K} = 3.42$$

Departure angle from complex poles. Let  $s \approx -1 + j2.45$  (near the upper complex pole), and evaluate the angle condition (angle of vectors from poles to s minus angle of vectors from zeros to s):

$$112.2^{\circ} + \theta + 90^{\circ} - 31.5^{\circ} = \pm 180^{\circ} \implies \theta = 9.3^{\circ}$$







# References



Nise, N. S. (2015). Control Systems Engineering. Wiley, 7 edition.