

Cashew



User: Classify the defect on the cashew. Choose from the following possible defects: Color, Broken, Scratch, Hole, Misplaced.

GenAU: I am examining the object for the following defects: Color, Broken, Scratch, Hole, Misplaced.
Status: the cashew is whole and not broken; the surface is smooth and not scuffed or scratched; there are no holes or openings on the shell; the cashew is in its correct position and orientation; a dark spot on the surface of the cashew. This is a sign for a Color defect.
Final Answer: Color
`[SEG_defect]` `[SEG_normal]`.


Pipe fryum



User: Classify the defect on the pipe fryum. Choose from the following possible defects: Color, Broken, Scratch, Hole, Misplaced.

GenAU: Upon inspecting the pipe fryum for Color, Broken, Scratch, Misplaced, Hole, I have confirmed that the surface has a uniform, natural color; the surface is smooth and free of scratches or abrasions; there are no holes or perforations on the surface; two fryums are present and in contact with one another. This is a clear instance of Misplaced defect.
Final Answer: Misplaced
`[SEG_defect]` `[SEG_normal]`.

PCB



User: Classify the defect on the pcb. Choose from the following possible defects: Bent, Contamination, Missing, Scratch.

GenAU: I am examining the object for the following defects: Bent, Contamination, Missing, Scratch.
Status: all three black ICs are present; the surface is clean and free of excess solder; there are no scratches or abrasions on the blue surface; the top row pins are curved. This is a sign for a Bent defect.
Final Answer: Bent
`[SEG_defect]` `[SEG_normal]`.