Calibration frame: 100 mm x 100 mm grid Digitize frame in the plane of interest.

- 0) Print file and verify dimensions with a ruler.
- 1) Set Nmarkers to 4.
- 2) Set markers to "Dark Color" in the "MT2D Marker Configurator"
- 3) Track 50 to 100 frames.
- 4) Save: Files > Save DLT Calibration File (enter the coordinates as shown)

[0,100] [100,100]





[0,0] [100,0]