

Revised December 2013

Document #: 282391

INSPECTION OFFICER ORDER NO. KAR - 002 - 2014 - 7002 - 1

IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT, AN ORDER UNDER SECTION 51.1

Full name of the recipient				
is employed by (working on behalf of the Landowner, and is a				
person/company conducting an excavation or construction on or near a facility located at				
Queocc				
On <u>6 October 2014 1045 hrs (MST)</u> , the undersigned <i>National Energy Board</i> Inspection Officer received information from Montreal Pipelines Ltd./Portland Pipeline Corporation that the above contractor, working on behalf of landowner conducted unauthorized excavation activity within 30 metres of the Montreal Pipelines Ltd. pipeline(s) and did not cease activity when requested to do so by Montreal Pipelines Ltd. at the above noted address on 6 October 2014.				
Location on R.O.W., compressor, pump or meter station				
The Inspection Officer has reasonable grounds to believe that: <u>As this excavation activity is unauthorized, the work was conducted in contravention of the Pipeline Crossing Regulations, Part I (Regulations); and the work will continue in contravention of the Regulations.</u>				
the inspection officer shall describe the grounds for making the order				
the inspection officer shall describe the grounds for making the order				
Based on the above mentioned, the Inspection Officer has reasonable grounds to believe that a hazard to the safety or security of the public, or employees of a company or a detriment to property or the environment is being or will be caused by the construction, operation, maintenance or abandonment of the pipeline, or excavation activity or construction of a facility set out in paragraph 49(2)(a) of the National Energy Board Act.				
Therefore,is HEREBY ORDERED,				
pursuant to sections 51.1 and 51.1(2) of the National Energy Board Act, to				
<ul> <li>         ⊠ take measures specified below for guarding the safety or security of the public or employees or protecting property or the environment     </li> <li>         ∑ Suspend work until the hazard or detrimental situation has been remedied to the satisfaction of the inspection officer; or the order is stayed or rescinded by the Board     </li> </ul>				
Specified Measures: <u>Until such time that it can be verified that the proposed work can be resumed in compliance with the Regulations and without jeopardizing the safety of the public and the environment, the Inspection Officer orders the recipient of this Order cease all excavation activities within 30 metres of the Montreal Pipelines Ltd. pipeline(s). The recipient is to provide written verification to the Inspection Officer that they will work in compliance with the Regulations no later than 20 October 2014.</u>				

Activity or Incident #: \_\_\_\_\_

**Canadä** 





## Office national de l'énergie

Inspection Officer		#1554	5
	Name	IO Designation #	Telephone
	08 October 2014	5 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	Date	Signature	
	517 10th Avenue SW Calgary AB T2R 0A8		