Las Positas College 3000 Campus Hill Drive Livermore, CA 94551-7650 (925) 424-1000 (925) 443-0742 (Fax)

Course Outline for WLDT 61BL

ADV STICK, FLUX-CORE SKILLS

Effective: Fall 2008

I. CATALOG DESCRIPTION:

WLDT 61BL — ADV STICK, FLUX-CORE SKILLS — 2.00 units

Advanced skills in Stick (SMAW) and Flux-core (FCAW) welding of steel in the horizontal, vertical and overhead positions to A.W.S. codes. Safety and proper use of SMAW and FCAW equipment, oxy-fuel welding and cutting, plasma cutting. Blueprint usage in welding shop environment. Pipe and tubing fit-up and welding.

2.00 Units Lab

<u>Prerequisite</u>

WLDT 61AL - Beginning SMAW and FCAW Skills Lab with a minimum grade of C

Corequisite

WLDT 61A - Beginning SMAW and FCAW Theory

WLDT 61B - Advanced SMAW and FCAW Theory

Grading Methods:

Letter or P/NP

Discipline:

MIN Lab Hours: 108.00 **Total Hours:** 108.00

- II. NUMBER OF TIMES COURSE MAY BE TAKEN FOR CREDIT: 4
- III. PREREQUISITE AND/OR ADVISORY SKILLS:

Before entering the course a student should be able to:

A. WLDT61AL

IV. MEASURABLE OBJECTIVES:

Upon completion of this course, the student should be able to:

- A. Demonstrate and describe safe use of advanced equipment associated with:
 - Shielded Metal Arc Welding (SMAW); Flux-core Arc Welding (FCAW)

 - 3. Plasma cutting
- 4. Oxy-fuel cutting
 5. Carbon arc cutting
 B. Describe the uses and limitations of each process;
- C. Classify proper electrode and wire selection for applications; D. Recognize common metals;
- D. Recognize common metals;
 E. Demonstrate FCAW, SMAW welded plate steel in the horizontal, vertical and overhead positions to AWS specifications;
 F. Perform circumferential welds in all positions;
 G. Outline the uses and limitations of Constant Current and constant voltage power sources;
 H. Operate plasma and oxy-fuel cut manually in all positions;
 I. Employ Oxy-fuel cutting with a shape cutting machine;
 J. Identify and practice safe practices in the welding shop;
 K. Use advanced blueprints to make parts;
 I. Safely operate advanced welding support equipment

- L. Safely operate advanced welding support equipment.

V. CONTENT:

- A. Advanced equipment associated with each welding/cutting process covered B. Uses and limitations of each process covered
- C. Electrode and wire selection for different applications

- D. Common metals
- FCAW, SMAW welded plate steel in the horizontal, vertical and overhead positions to AWS specifications
- F. Circumferential welds in all positions
 G. Welding power supplies, AC and DC, constant current and constant voltage
 H. Plasma and oxy-fuel cutting in all positions
- Machine cutting of shapes
 J. Safe handling and use
 1. Shielded Metal Arc (SMAW)
- - Flux core Arc (FCAW)
 - Oxy-fuel cutting
 - Plasma cutting
- 5. Carbon arc cutting
 K. Advanced blueprint usage in the welding shop
 L. Advanced welding support equipment safe use and application

VI. METHODS OF INSTRUCTION:

- A. Lecture -B. Discussion -
- C. Correlation with real world industrial applications
- D. Visual aids
- One-on-one, hands-on instruction
- F. Group demonstration

VII. TYPICAL ASSIGNMENTS:

A. Welding samples using different welding processes 1. Shielded Metal Arc Welding (SMAW) 2. Flux-core Arc Welding (FCAW) B. Welding samples using different welding joints 1. Butt joint 2. Tee joint 3. Lap joint 4. Corner joint 5. Edge joint C. Welding samples using different positions 1. Horizontal 2. Vertical 3. Overhead D. Welding Samples using different materials 1. Carbon Steel 2. Stainless Steel E. Cutting samples using hand held oxy-acetylene cutting torch F. Cutting samples using semi-automated oxy-acetylene cutting torch G. Cutting samples using hand held plasma arc cutting torch

VIII. EVALUATION:

A. Methods

- Class Participation
- 2. Lab Activities
- 3. Other:
 - a. Methods:

 - Participation
 Workmanship samples
 - 3. Safe operation in the laboratory environment and the proper use of shop equipment

B. Frequency

- Frequency:
 a. Participation will be evaluated daily.

 A participation will be evaluated daily.

 A participation will be evaluated daily.

 A participation will be evaluated daily.
 - b. Workmanship samples will be submitted for grading as completed over the duration of the semester.
 - c. Safety and proper use of tools will be evaluated on a daily basis.

IX. TYPICAL TEXTS:

1. Texts assigned in corequisite lecture course.

X. OTHER MATERIALS REQUIRED OF STUDENTS:

- A. Personal Protective Equipment B. Safety Glasses (ANSI Z87.1)

- C. Leather welding gloves
 D. Long sleeve shirt or jacket
 E. Leather shoes or boots