Site Inspection Note

Northbrook Facilities Authority - Facilities Compliance Team

Site: Eastwick Central Depot. Date of inspection: 22/04/2025. Inspector: Grace Okafor.

The inspection followed a complaint about a warm chilled delivery received on 17/04/2025. Bay 3 was inspected together with the trailer that made the delivery. The bay's dock shelter was in good condition and the door-open alarm worked when tested.

The trailer's left-hand door seal was torn along about 60 cm of its length. A torn seal of this size lets warm air into the load space whenever the trailer is moving, and is consistent with the temperature rise recorded by the trailer's logger.

The depot's own probe was within calibration; its last calibration was on 03/02/2025. The goods-in sheet for 17/04/2025 records three core readings above 8°C, signed by the stores manager.

Conclusion: the temperature excursion was caused by the damaged trailer seal, not by the depot's equipment or procedures. The trailer should not return to chilled service until the seal has been replaced.

Addendum (added 30/04/2025): the replacement door seal was fitted on 29/04/2025 by the contractor Brightwell Seals, job reference BW-7741. The trailer was re-inspected and returned to chilled service on 01/05/2025.