
AC_C695A_SEAT
cabin tone level at the mic seat (dB)
110
100
90
80
1.0
1.5
2.0
2.5
3.0
harmonic of the blade-passage frequency
measured mic 3 (App. B)
measured mic 6 (App. B)
PAIN point form at the mic seat (per engine)
error per point (no criterion) — clipped
PAIN − measured (dB)
20
10
0
−10
−20
1.0
1.5
2.0
2.5
3.0
harmonic of the blade-passage frequency
H1
H2
H3